
急傾斜地の崩壊区域調書



急傾斜地の崩壊区域調書

箇所名

東中山1

所在地

船橋市東中山2丁目

様式5-5 危害のおそれのある土地等の座標一覧

箇所番号

I -022K2201

急傾斜地の位置

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	10600.30	-31457.41	Y28	-31513.97	10555.31	R1	-31469.95	10600.71			
Y2	10620.79	-31464.54	Y29	-31510.58	10550.57	R2	-31475.70	10619.81			
Y3	10637.36	-31461.58	Y30	-31497.59	10540.20	R3	-31473.15	10636.74			
Y4	10637.00	-31468.45	Y31	-31480.32	10552.07	R4	-31479.95	10636.39			
Y5	10636.39	-31479.95	Y32	-31471.79	10562.99	R5	-31487.01	10636.02			
Y6	10635.57	-31495.44	Y33	-31468.03	10571.97	R6	-31487.96	10618.73			
Y7	10635.33	-31499.89	Y34	-31460.02	10588.15	R7	-31484.60	10601.17			
Y8	10635.04	-31505.43				R8	-31486.62	10594.41			
Y9	10617.32	-31504.00				R9	-31489.55	10587.95			
Y10	10600.95	-31501.64				R10	-31495.36	10578.54			
Y11	10599.01	-31502.64				R11	-31502.10	10570.05			
Y12	10594.91	-31504.31				R12	-31503.24	10568.92			
Y13	10587.67	-31509.20				R13	-31506.75	10569.03			
Y14	10584.14	-31510.79				R14	-31512.86	10571.21			
Y15	10583.72	-31511.36				R15	-31512.80	10569.66			
Y16	10581.44	-31511.62				R16	-31512.80	10569.55			
Y17	10584.01	-31516.67				R17	-31513.15	10565.28			
Y18	10569.85	-31524.69				R18	-31507.85	10562.01			
Y19	10569.82	-31524.70				R19	-31500.04	10553.56			
Y20	10571.86	-31526.84				R20	-31490.63	10560.36			
Y21	10568.67	-31527.25				R21	-31482.83	10570.27			
Y22	10561.95	-31528.12	_			R22	-31478.17	10579.56	_		
Y23	10561.94	-31528.12				R23	-31472.45	10590.99			
Y24	10559.19	-31528.47	_				_		_		
Y25	10551.83	-31529.42									
Y26	10550.63	-31518.40									