


急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度 令和5年度

急傾斜地の位置 箇所番号 I-031K2117 箇所名 千駄堀6 所在地 松戸市千駄堀

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-21647.67	9201.40	Y31	-22115.70	9271.99	R1	-21652.89	9202.42	R30	-21772.18	9140.89
Y2	-21649.92	9181.58	Y32	-22129.44	9276.18	R2	-21659.25	9183.58	R31	-21754.99	9136.67
Y3	-21653.14	9168.16	Y33	-22127.20	9282.91	R3	-21661.95	9171.77	R32	-21736.85	9137.97
Y4	-21652.81	9138.86	Y34	-22125.51	9287.98	R4	-21670.49	9152.41	R33	-21722.84	9134.42
Y5	-21654.89	9132.81	Y35	-22124.44	9291.20	R5	-21674.74	9144.38	R34	-21711.85	9124.52
Y6	-21689.15	9138.47	Y36	-22123.63	9293.62	R6	-21695.10	9147.55	R35	-21711.78	9124.27
Y7	-21689.15	9138.47	Y37	-22121.27	9300.68	R7	-21695.10	9147.55	R36	-21711.46	9123.03
Y8	-21689.15	9138.47	Y38	-22101.09	9294.61	R8	-21697.70	9151.52	R37	-21710.36	9118.73
Y9	-21716.40	9139.37	Y39	-22081.92	9288.50	R9	-21697.70	9151.52			
Y10	-21715.77	9141.53	Y40	-22065.08	9282.29	R10	-21698.80	9153.20			
Y11	-21716.18	9142.14	Y41	-22059.54	9281.11	R11	-21698.80	9153.20			
Y12	-21716.53	9142.35	Y42	-22046.31	9276.94	R12	-21695.37	9156.41			
Y13	-21719.38	9143.64	Y43	-22033.97	9272.91	R13	-21689.18	9166.73			
Y14	-21726.09	9146.35	Y44	-22015.27	9267.17	R14	-21670.59	9175.31			
Y15	-21750.94	9154.44	Y45	-21996.43	9260.96	R15	-21668.31	9185.52			
Y16	-21782.37	9164.65	Y46	-21978.83	9255.40	R16	-21657.49	9203.33			
Y17	-21797.03	9169.57	Y47	-21961.18	9248.68	R17	-21655.26	9202.89			
Y18	-21821.00	9177.24	Y48	-21955.57	9247.30						
Y19	-21863.07	9190.63	Y49	-21940.67	9242.29	R18	-21710.08	9117.61			
Y20	-21882.39	9196.88	Y50	-21921.74	9236.75	R19	-21725.19	9124.09			
Y21	-21907.52	9205.03	Y51	-21905.17	9232.19	R20	-21739.34	9123.75			
Y22	-21935.78	9214.13	Y52	-21894.39	9228.97	R21	-21755.31	9130.22			
Y23	-21957.69	9220.80	Y53	-21874.86	9222.88	R22	-21772.18	9129.32			
Y24	-21983.78	9229.31	Y54	-21856.16	9216.93	R23	-21788.61	9137.05			
Y25	-22003.73	9236.41	Y55	-21837.85	9211.27	R24	-21806.29	9136.45			
Y26	-22020.55	9241.80	Y56	-21818.31	9205.21	R25	-21819.57	9136.92			
Y27	-22052.99	9251.91	Y57	-21798.13	9197.64	R26	-21819.67	9137.71			
Y28	-22064.05	9255.14	Y58	-21782.40	9192.31	R27	-21820.16	9141.23			
Y29	-22087.96	9263.06	Y59	-21779.31	9191.20	R28	-21806.92	9144.31			
Y30	-22100.69	9267.22	Y60	-21762.42	9187.00	R29	-21788.65	9140.84			

平面直角座標系: 第Ⅸ系(測地成果2011)

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度 令和5年度

急傾斜地の位置 箇所番号 I-031K2117 箇所名 千駄堀6 所在地 松戸市千駄堀

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y61	-21743.15	9180.57	Y90	-21782.42	9180.54						
Y62	-21726.34	9174.89	Y91	-21765.51	9175.29						
Y63	-21707.31	9168.50	Y92	-21768.69	9166.37						
Y64	-21702.35	9176.81	Y93	-21769.80	9163.28						
Y65	-21684.70	9181.09	Y94	-21771.31	9159.04						
Y66	-21683.16	9188.71	Y95	-21772.82	9154.80						
Y67	-21673.19	9206.41	Y96	-21774.66	9149.62						
Y68	-21669.81	9205.75	Y97	-21792.76	9155.10						
Y69	-21663.37	9204.48	Y98	-21795.98	9156.25						
Y70	-21657.49	9203.33	Y99	-21812.99	9162.37						
Y71	-21655.26	9202.89	Y100	-21831.56	9167.97						
			Y101	-21852.14	9174.44						
Y72	-22118.92	9287.99	Y102	-21871.25	9180.57						
Y73	-22105.84	9283.76	Y103	-21891.20	9187.54						
Y74	-22088.81	9278.27	Y104	-21907.00	9193.04						
Y75	-22075.89	9274.13	Y105	-21924.33	9199.31						
Y76	-22067.19	9271.11	Y106	-21941.55	9204.99						
Y77	-22062.07	9269.88	Y107	-21957.26	9209.90						
Y78	-22035.40	9261.35	Y108	-21968.43	9212.27						
Y79	-22015.72	9255.28	Y109	-21974.42	9214.64						
Y80	-22000.04	9250.35	Y110	-21991.40	9220.17						
Y81	-21975.83	9242.42	Y111	-22009.98	9226.42						
Y82	-21964.25	9238.53	Y112	-22029.74	9232.48						
Y83	-21959.24	9237.42	Y113	-22046.60	9237.46						
Y84	-21924.16	9226.18	Y114	-22063.74	9242.99						
Y85	-21895.94	9217.18	Y115	-22070.84	9244.92						
Y86	-21868.97	9208.36	Y116	-22088.66	9250.52						
Y87	-21844.29	9200.71	Y117	-22106.93	9256.79						
Y88	-21816.39	9192.05	Y118	-22126.53	9263.71						
Y89	-21793.01	9184.31	Y119	-22126.48	9263.89						

平面直角座標系: 第Ⅸ系(測地成果2011)

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度 令和5年度

急傾斜地の位置 箇所番号 I-031K2117 箇所名 千駄堀6 所在地 松戸市千駄堀

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y120	-22123.54	9273.25	Y149	-21711.78	9124.27						
Y121	-22122.50	9276.59	Y150	-21711.46	9123.03						
Y122	-22121.45	9279.92	Y151	-21710.36	9118.73						
Y123	-21708.35	9110.82									
Y124	-21727.47	9114.06									
Y125	-21741.55	9111.19									
Y126	-21755.67	9122.81									
Y127	-21772.18	9118.53									
Y128	-21788.51	9129.23									
Y129	-21805.71	9129.12									
Y130	-21818.80	9131.32									
Y131	-21819.67	9137.71									
Y132	-21820.16	9141.23									
Y133	-21820.84	9146.18									
Y134	-21821.53	9151.20									
Y135	-21822.20	9156.09									
Y136	-21808.23	9160.62									
Y137	-21788.81	9154.23									
Y138	-21772.18	9156.73									
Y139	-21770.10	9154.68									
Y140	-21750.00	9149.55									
Y141	-21741.38	9147.35									
Y142	-21715.99	9140.89									
Y143	-21715.65	9140.02									
Y144	-21714.84	9136.58									
Y145	-21713.53	9130.99									
Y146	-21713.35	9130.28									
Y147	-21712.97	9128.74									
Y148	-21712.47	9126.69									

平面直角座標系: 第Ⅸ系(測地成果2011)