
## 急傾斜地の崩壊区域調書



## 急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度

令和5年度

急傾斜地の位置 | 箇所番号 | I-031K2128 | 箇所名 | 大谷口9 | **所在地** | 松戸市大谷口

							著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	
Y1	-18361.75	7880.09	Y30	-18410.28	7863.45	R1	-18361.48	7885.32				
Y2	-18364.77	7875.10	Y31	-18405.16	7863.08	R2	-18364.95	7882.73				
Y3	-18373.86	7873.16	Y32	-18400.30	7862.73	R3	-18376.62	7880.57				
Y4	-18393.37	7875.10	Y33	-18393.72	7862.26	R4	-18395.33	7879.95				
Y5	-18394.46	7877.79	Y34	-18387.49	7861.81	R5	-18397.12	7884.36				
Y6	-18397.12	7884.36				R6	-18379.70	7888.86				
Y7	-18399.83	7891.03				R7	-18365.14	7891.24				
Y8	-18400.60	7892.92				R8	-18361.22	7890.08				
Y9	-18403.59	7900.30										
Y10	-18385.57	7904.66				R9	-18388.97	7861.92				
Y11	-18365.54	7908.29				R10	-18387.67	7848.66				
Y12	-18360.31	7907.25				R11	-18392.99	7837.00				
Y13	-18360.59	7901.92				R12	-18403.23	7831.55				
Y14	-18360.84	7897.27				R13	-18420.54	7831.13				
Y15	-18361.22	7890.08				R14	-18420.58	7836.47				
Y16	-18361.61	7882.87				R15	-18420.59	7837.52				
						R16	-18407.43	7839.40				
Y17	-18383.75	7861.54				R17	-18400.38	7842.47				
Y18	-18381.69	7845.73				R18	-18393.94	7851.73				
Y19	-18384.75	7830.90				R19	-18393.72	7862.26				
Y20	-18399.17	7823.94										
Y21	-18420.50	7824.87										
Y22	-18420.51	7826.60										
Y23	-18420.58	7836.47										
Y24	-18420.63	7844.07										
Y25	-18420.67	7849.43										
Y26	-18420.70	7854.07										
Y27	-18414.82	7853.22										
Y28	-18412.23	7851.25										
Y29	-18408.81	7859.02										

平面直角座標系:第IX系(測地成果2011)