急傾斜地の崩壊区域調書

-4 危害のおそれのあ)る工地寺の座標位	I 0011/0100	ケミカ	/ -/-/-/-/- -	ニナル		調査年度	2023
急傾斜地の位置	箇所番号	I -031K2138	箇所名	仲井町1	所在地	松戸市仲井町	I J 🗏	
								Ŋ
								•
								,
				D10				
			V	Y20 R18 R19 Y21				
			Y	R17.\\\				
				R17				
			Y18 <					
			Y17-	R20				
			Y16	D15				
				R15 R21				
			Y15	2	Y23			
			Y14		1			
				D12 V2	Y1			
				R10R11/ R12 Y2 Y3				
			Y13 🔾	R9				
			113	1				
				R1	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\			
			\	DO IR	2			
			Y1	149.	R3			
			Y1	R7	R4			
					M			
					/Ye			
				Y11 Y	R5 Y7			
				Y10 Y9	Bl _{R6}			
				Y10				
1:1,000								
25	50 m							

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度

2023

急傾斜地の位置 箇所番号	I -031K2138	箇所名	<i>仲井町1</i>	所在地	松戸市仲井町1丁目
--------------	-------------	-----	-------------	-----	-----------

危害のおそれのある区域の座標(土砂災害警戒区域)					著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)						
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-23373.53	7863.79				R1	-23389.09	7848.93			
Y2	-23385.42	7851.65				R2	-23405.42	7859.95			
Y3	-23382.69	7857.33				R3	-23405.00	7865.47			
Y4	-23398.87	7867.48				R4	-23409.28	7861.89			
Y5	-23398.36	7871.02				R5	-23409.87	7861.40			
Y6	-23409.28	7861.89				R6	-23412.25	7859.41			
Y7	-23409.87	7861.40				R7	-23410.00	7854.68			
Y8	-23417.01	7855.44				R8	-23394.34	7842.05			
Y9	-23417.88	7854.71				R9	-23385.92	7833.81			
Y10	-23424.68	7849.03				R10	-23385.85	7836.26			
Y11	-23419.14	7844.16				R11	-23385.77	7839.41			
Y12	-23403.06	7830.60				R12	-23385.69	7841.99			
Y13	-23386.34	7819.26				R13	-23389.09	7848.93			
Y14	-23368.32	7835.36									
Y15	-23364.30	7828.48				R14	-23355.97	7839.98			
Y16	-23357.63	7823.53				R15	-23356.72	7838.94			
Y17	-23354.12	7828.32				R16	-23347.63	7837.15			
Y18	-23351.71	7831.59				R17	-23346.32	7838.93			
Y19	-23346.32	7838.93				R18	-23345.39	7840.21			
Y20	-23345.39	7840.21				R19	-23342.85	7843.65			
Y21	-23338.51	7849.57				R20	-23353.94	7842.79			
Y22	-23347.52	7851.64				R21	-23355.97	7839.98			
Y23 -23373.53	-23373.53	7863.79									

平面直角座標系:第IX系(測地成果2011)