
## 急 傾 斜 地 の 崩 壊 区 域 調 書



## 急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地等の座標一覧


調査年度 2024

| 急傾斜地の位置 | 箇所番号 | I -042K2002(-2) | 箇所名 | つくし野4 | 所在地 | 我孫子市つくし | ン野2丁目 |
|---------|------|-----------------|-----|-------|-----|---------|-------|

|      | 危害のおそれのある土地の座標 |          |      |      |      |  |  |  |  |
|------|----------------|----------|------|------|------|--|--|--|--|
| 地点記号 | X(m)           | Y(m)     | 地点記号 | X(m) | Y(m) |  |  |  |  |
| Y-1  | -13387.31      | 15922.1  |      |      |      |  |  |  |  |
| Y-2  | -13400.46      | 15928.01 |      |      |      |  |  |  |  |
| Y-3  | -13413.46      | 15934.89 |      |      |      |  |  |  |  |
| Y-4  | -13417.34      | 15929.19 |      |      |      |  |  |  |  |
| Y-5  | -13419.09      | 15926.63 |      |      |      |  |  |  |  |
| Y-6  | -13420.45      | 15924.64 |      |      |      |  |  |  |  |
| Y-7  | -13421.62      | 15922.93 |      |      |      |  |  |  |  |
| Y-8  | -13426.08      | 15916.39 |      |      |      |  |  |  |  |
| Y-9  | -13410.92      | 15907.53 |      |      |      |  |  |  |  |
| Y-10 | -13394.87      | 15900.38 |      |      |      |  |  |  |  |
| Y-11 | -13394.18      | 15898.08 |      |      |      |  |  |  |  |
| Y-12 | -13394.16      | 15898.05 |      |      |      |  |  |  |  |
| Y-13 | -13395.23      | 15896.64 |      |      |      |  |  |  |  |
| Y-14 | -13397.47      | 15887.1  |      |      |      |  |  |  |  |
| Y-15 | -13401.32      | 15871.05 |      |      |      |  |  |  |  |
| Y-16 | -13396.73      | 15860.02 |      |      |      |  |  |  |  |
| Y-17 | -13394         | 15859.45 |      |      |      |  |  |  |  |
| Y-18 | -13386.94      | 15857.97 |      |      |      |  |  |  |  |
| Y-19 | -13379.89      | 15856.49 |      |      |      |  |  |  |  |
| Y-20 | -13376.39      | 15855.76 |      |      |      |  |  |  |  |
| Y-21 | -13370.1       | 15854.45 |      |      |      |  |  |  |  |
| Y-22 | -13362.22      | 15863.72 |      |      |      |  |  |  |  |
| Y-23 | -13359.87      | 15881.57 |      |      |      |  |  |  |  |
| Y-24 | -13359.06      | 15904.57 |      |      |      |  |  |  |  |
| Y-25 | -13371.31      | 15913.17 |      |      |      |  |  |  |  |
| Y-26 | -13371.32      | 15913.16 |      |      |      |  |  |  |  |
|      |                |          |      |      |      |  |  |  |  |
|      |                |          |      |      |      |  |  |  |  |

| 著しい危害のおそれのある土地の座標 |           |          |      |      |      |  |  |
|-------------------|-----------|----------|------|------|------|--|--|
| 地点記号              | X(m)      | Y(m)     | 地点記号 | X(m) | Y(m) |  |  |
| R-1               | -13376.88 | 15909.48 |      |      |      |  |  |
| R-2               | -13379.98 | 15907.43 |      |      |      |  |  |
| R-3               | -13380.21 | 15907.28 |      |      |      |  |  |
| R-4               | -13377.66 | 15900.49 |      |      |      |  |  |
| R-5               | -13380.9  | 15884.66 |      |      |      |  |  |
| R-6               | -13383.98 | 15867.8  |      |      |      |  |  |
| R-7               | -13379.89 | 15856.49 |      |      |      |  |  |
| R-8               | -13376.39 | 15855.76 |      |      |      |  |  |
| R-9               | -13375.23 | 15855.52 |      |      |      |  |  |
| R-10              | -13372.2  | 15865.59 |      |      |      |  |  |
| R-11              | -13369.67 | 15883    |      |      |      |  |  |
| R-12              | -13367.69 | 15902.68 |      |      |      |  |  |
| R-13              | -13375.88 | 15910.14 |      |      |      |  |  |
|                   |           |          |      |      |      |  |  |
|                   |           |          |      |      |      |  |  |
|                   |           |          |      |      |      |  |  |
|                   |           |          |      |      |      |  |  |
|                   |           |          |      |      |      |  |  |
|                   |           |          |      |      |      |  |  |
|                   |           |          |      |      |      |  |  |
|                   |           |          |      |      |      |  |  |
|                   |           |          |      |      |      |  |  |
|                   |           |          |      |      |      |  |  |
|                   |           |          |      |      |      |  |  |
|                   |           |          |      |      |      |  |  |
|                   |           |          |      |      |      |  |  |
|                   |           |          |      |      |      |  |  |
|                   |           |          |      |      |      |  |  |

## 急傾斜地の崩壊区域調書



## 急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地等の座標一覧

Y-13

Y-14 Y-15

Y-16

Y-17

Y-18

Y-19

Y-20

Y-21 Y-22 -13430.86

-13420.4

-13412.12

-13413.81

-13405.15

-13400.62

-13395.99

-13395.23 -13393.83

-13392.97

15958.13

15941.77

15938.36

15935.5

15927.96

15925.62

15932.87 15934.05

15936.24

15937.59

調査年度 2024

| っ 厄告のおて | れのめる工地寺   | の座標一頁         |              |       |      |       |      |         |        | 調宜平度  | 20     |
|---------|-----------|---------------|--------------|-------|------|-------|------|---------|--------|-------|--------|
| 類斜地の位置  | 箇所都       | 番号 <i>I</i> - | -042K2002(=3 | 3) 箇所 | 名    | つくし野4 |      | 所在地     |        | 我孫子市つ | くし野2丁目 |
|         |           |               |              |       |      | F     |      |         |        |       |        |
|         | 危害        | 害のおそれの        | ある土地の座       | 標     |      |       | 著しい  | い危害のおそれ | れのある土地 | の座標   |        |
| 地点記号    | X(m)      | Y(m)          | 地点記号         | X(m)  | Y(m) | 地点記号  | X(m) | Y(m)    | 地点記号   | X(m)  | Y(m)   |
| Y-1     | -13388.45 | 15944.67      |              |       |      |       |      |         |        |       |        |
| Y-2     | -13392.89 | 15948.32      |              |       |      |       |      |         |        |       |        |
| Y-3     | -13392.7  | 15952.79      |              |       |      |       |      |         |        |       |        |
| Y-4     | -13406.87 | 15961.34      |              |       |      |       |      |         |        |       |        |
| Y−5     | -13407.54 | 15965.96      |              |       |      |       |      |         |        |       |        |
| Y-6     | -13414.49 | 15981.7       |              |       |      |       |      |         |        |       |        |
| Y-7     | -13430.72 | 15979.89      |              |       |      |       |      |         |        |       |        |
| Y-8     | -13430.17 | 15972.57      |              |       |      |       |      |         |        |       |        |
| Y-9     | -13429.97 | 15969.92      |              |       |      |       |      |         |        |       |        |
| Y-10    | -13429.78 | 15967.33      |              |       |      |       |      |         |        |       |        |
| Y-11    | -13429.7  | 15966.18      |              |       |      |       |      |         |        |       |        |
| Y-12    | -13429.2  | 15959.58      |              |       |      |       |      |         |        |       |        |

| X(m) | Y(m) |  |
|------|------|--|
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |
|      |      |  |

|      | 著しい  | ・危害のおそ | れのある土地の | )座標  |      |
|------|------|--------|---------|------|------|
| 地点記号 | X(m) | Y(m)   | 地点記号    | X(m) | Y(m) |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |
|      |      |        |         |      |      |

平面直角座標系:第IX系(測地成果2011)