

急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度

令和5年度

急傾斜地の位置

箇所番号


I-124K2016

箇所名

久保19

所在地

夷隅郡御宿町久保



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度 令和5年度

急傾斜地の位置		箇所番号	I-124K2016		箇所名	久保19		所在地	夷隅郡御宿町久保		
危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-88531.31	47876.62	Y-31	-88502.10	47864.66	R-1	-88495.52	47861.96			
Y-2	-88517.24	47874.99				R-2	-88478.59	47869.91			
Y-3	-88529.30	47886.10				R-3	-88491.25	47881.29			
Y-4	-88528.95	47903.88				R-4	-88490.83	47898.71			
Y-5	-88526.32	47919.19				R-5	-88488.21	47913.45			
Y-6	-88519.46	47945.68				R-6	-88484.07	47930.56			
Y-7	-88508.11	47971.65				R-7	-88476.40	47949.07			
Y-8	-88466.94	47990.82				R-8	-88451.52	47954.39			
Y-9	-88447.44	47944.77				R-9	-88447.44	47944.77			
Y-10	-88446.35	47942.19				R-10	-88446.35	47942.19			
Y-11	-88442.70	47930.60				R-11	-88442.70	47930.60			
Y-12	-88441.43	47921.55				R-12	-88441.43	47921.55			
Y-13	-88440.16	47912.98				R-13	-88440.16	47912.98			
Y-14	-88438.41	47907.58				R-14	-88439.75	47911.71			
Y-15	-88436.70	47904.67				R-15	-88441.14	47909.57			
Y-16	-88432.70	47897.90				R-16	-88442.94	47906.56			
Y-17	-88431.61	47896.06				R-17	-88443.38	47905.57			
Y-18	-88431.75	47896.06				R-18	-88443.36	47893.67			
Y-19	-88432.05	47895.65				R-19	-88438.97	47878.17			
Y-20	-88432.16	47895.39				R-20	-88438.14	47872.68			
Y-21	-88430.12	47888.81				R-21	-88429.51	47872.28			
Y-22	-88424.39	47878.85				R-22	-88461.09	47860.82			
Y-23	-88424.34	47876.91				R-23	-88476.84	47855.80			
Y-24	-88413.71	47878.01				R-24	-88482.39	47856.59			
Y-25	-88420.61	47875.51				R-25	-88485.03	47857.67			
Y-26	-88423.11	47874.60									
Y-27	-88461.09	47860.82									
Y-28	-88476.84	47855.80									
Y-29	-88482.39	47856.59									
Y-30	-88485.03	47857.67									

平面直角座標系：第Ⅸ区(測地成果2011)

平面直角座標系：第Ⅸ系(測地成果2011)