

急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度

2023

急傾斜地の位置

箇所番号


I-132K2059-1

箇所名

宮1

所在地

鴨川市宮



1:1,000

0 25 50 m

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度	2023
------	------

急傾斜地の位置	箇所番号	I-132K2059-1	箇所名	宮1	所在地	鶴川市宮
---------	------	--------------	-----	----	-----	------

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-100452.07	22863.40				R1	-100442.40	22866.87			
Y2	-100464.38	22871.80				R2	-100449.23	22879.37			
Y3	-100486.75	22860.65				R3	-100451.64	22878.20			
Y4	-100492.32	22881.97				R4	-100453.99	22889.70			
Y5	-100491.65	22909.00				R5	-100452.55	22906.10			
Y6	-100485.98	22932.57				R6	-100448.08	22921.50			
Y7	-100479.76	22945.18				R7	-100444.83	22930.34			
Y8	-100463.33	22966.72				R8	-100436.73	22942.31			
Y9	-100446.17	22979.37				R9	-100427.21	22950.83			
Y10	-100433.23	22983.54				R10	-100419.25	22956.55			
Y11	-100433.23	22983.54				R11	-100419.25	22956.55			
Y12	-100391.25	22957.92				R12	-100419.25	22956.55			
Y13	-100391.65	22956.68				R13	-100395.27	22945.56			
Y14	-100397.44	22938.90				R14	-100397.44	22938.90			
Y15	-100401.34	22926.91				R15	-100400.11	22930.68			
Y16	-100402.61	22922.40				R16	-100406.99	22928.84			
Y17	-100404.19	22916.83				R17	-100406.99	22928.84			
Y18	-100404.33	22916.36				R18	-100409.78	22924.56			
Y19	-100404.33	22916.36				R19	-100413.71	22921.19			
Y20	-100413.53	22908.46				R20	-100416.13	22917.94			
Y21	-100414.07	22907.84				R21	-100418.93	22912.99			
Y22	-100424.31	22895.98				R22	-100419.39	22905.54			
Y23	-100424.22	22895.89				R23	-100419.61	22904.57			
Y24	-100426.93	22875.87				R24	-100418.53	22902.66			
Y25	-100430.75	22871.05				R25	-100430.54	22888.75			
Y26	-100434.38	22869.75				R26	-100435.30	22886.38			
Y27	-100438.70	22868.20				R27	-100435.37	22886.31			
Y28	-100448.81	22864.57				R28	-100437.42	22868.66			
						R29	-100438.70	22868.20			

平面直角座標系：第Ⅸ区系(測地成果2011)

急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度

2023

急傾斜地の位置

箇所番号


I-132K2059-2

箇所名

宮1

所在地

鴨川市宮



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度	2023
------	------

急傾斜地の位置	箇所番号	I-132K2059-2	箇所名	宮1	所在地	鶴川市宮
---------	------	--------------	-----	----	-----	------

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-100461.46	22865.14	Y31	-100441.87	22893.78	R1	-100457.49	22876.78			
Y2	-100466.75	22874.75	Y32	-100439.88	22880.62	R2	-100465.28	22890.40			
Y3	-100475.72	22888.90	Y33	-100438.17	22870.51	R3	-100457.25	22904.73			
Y4	-100468.56	22906.26	Y34	-100447.91	22868.26	R4	-100454.29	22904.32			
Y5	-100460.43	22905.26	Y35	-100451.72	22867.39	R5	-100453.14	22904.17			
Y6	-100458.35	22915.90				R6	-100456.30	22891.70			
Y7	-100451.77	22934.92				R7	-100452.84	22877.79			
Y8	-100459.47	22938.74				R8	-100453.86	22877.57			
Y9	-100461.95	22958.81									
Y10	-100466.32	22982.77				R9	-100448.98	22933.73			
Y11	-100461.47	22988.16				R10	-100451.06	22952.79			
Y12	-100454.49	22982.56				R11	-100448.98	22969.61			
Y13	-100451.84	22982.36				R12	-100443.93	22974.08			
Y14	-100445.17	22989.14				R13	-100432.55	22980.89			
Y15	-100448.33	22996.40				R14	-100434.01	22984.63			
Y16	-100446.59	22997.29				R15	-100438.28	22992.52			
Y17	-100438.37	23001.51				R16	-100442.99	22999.14			
Y18	-100431.96	23004.79				R17	-100438.37	23001.51			
Y19	-100423.06	23009.34				R18	-100437.68	23001.86			
Y20	-100418.14	23002.39				R19	-100431.81	22995.69			
Y21	-100405.39	22996.97				R20	-100417.82	22991.61			
Y22	-100402.55	22978.60				R21	-100416.07	22979.63			
Y23	-100412.17	22948.60				R22	-100425.21	22959.06			
Y24	-100416.73	22945.13				R23	-100430.17	22955.33			
Y25	-100424.94	22938.34				R24	-100439.07	22946.16			
Y26	-100433.48	22926.33				R25	-100444.94	22931.80			
Y27	-100433.53	22926.23				R26	-100446.11	22932.36			
Y28	-100438.94	22910.25				R27	-100447.63	22933.09			
Y29	-100440.61	22902.49									
Y30	-100440.62	22902.47									

平面直角座標系：第Ⅸ区系(測地成果2011)

急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度

2023

急傾斜地の位置

箇所番号


I-132K2059-3

箇所名

宮1

所在地

鴨川市宮



1:1,000

0 25 50 m

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度	2023
------	------

急傾斜地の位置	箇所番号	I-132K2059-3	箇所名	宮1	所在地	鶴川市宮
---------	------	--------------	-----	----	-----	------

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-100551.18	23129.59				R1	-100518.21	23139.05			
Y2	-100547.69	23143.31				R2	-100516.70	23150.59			
Y3	-100545.15	23147.96				R3	-100517.30	23167.93			
Y4	-100552.34	23158.30				R4	-100526.78	23179.55			
Y5	-100552.34	23158.30				R5	-100534.20	23194.15			
Y6	-100529.14	23151.44				R6	-100528.46	23193.66			
Y7	-100529.68	23169.06				R7	-100525.01	23193.37			
Y8	-100542.78	23180.91				R8	-100507.75	23177.94			
Y9	-100542.45	23194.85				R9	-100503.27	23166.64			
Y10	-100528.46	23193.66				R10	-100503.20	23149.66			
Y11	-100516.47	23192.64				R11	-100488.92	23122.52			
Y12	-100506.50	23191.79				R12	-100488.92	23122.52			
Y13	-100489.84	23176.42				R13	-100508.79	23133.74			
Y14	-100486.83	23165.13				R14	-100508.79	23133.74			
Y15	-100487.25	23148.56				R15	-100514.12	23136.74			
Y16	-100477.17	23112.86				R16	-100514.12	23136.74			
Y17	-100477.17	23112.86				R17	-100518.21	23139.05			
Y18	-100477.17	23112.86									
Y19	-100474.71	23106.04									
Y20	-100460.92	23092.10									
Y21	-100460.81	23086.82									
Y22	-100462.33	23087.49									
Y23	-100469.97	23090.83									
Y24	-100477.99	23094.34									
Y25	-100482.09	23096.03									
Y26	-100487.49	23098.34									
Y27	-100506.29	23107.56									
Y28	-100518.61	23113.61									

平面直角座標系：第Ⅸ区系(測地成果2011)