

真里谷113

所在地

様式5-5 危害のおそれのある土地の座標一覧

箇所番号

I -141K2153-1

箇所名

急傾斜地の位置

調査年度

木更津市真里谷

令和5年度


	危害のおそれ	ιのある区域(	の座標(土砂災	炎害警戒区域	)	著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)						
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m	
Y-1	-70686.29	21859.46				R−1	-70683.87	21876.46				
Y-2	-70671.65	21841.05				R-2	-70667.61	21857.49				
Y-3	-70654.37	21809.30				R-3	-70650.74	21826.79				
Y-4	-70635.07	21796.43				R-4	-70632.88	21814.90				
Y−5	-70620.58	21791.88				R-5	-70618.24	21810.40				
Y-6	-70619.63	21799.36				R-6	-70610.79	21869.56				
Y-7	-70619.32	21801.81				R−7	-70610.15	21886.12				
Y-8	-70610.79	21869.56				R-8	-70609.77	21895.95				
Y-9	-70610.15	21886.12				R-9	-70623.56	21893.69				
Y-10	-70609.47	21903.57				R-10	-70639.36	21881.59				
Y-11	-70608.22	21936.08				R-11	-70656.56	21891.78				
Y-12	-70618.84	21933.54				R−12	-70681.25	21894.91				
Y-13	-70631.30	21920.40				R−13	-70682.32	21887.38				
Y-14	-70645.04	21926.60				R−14	-70682.41	21886.71				
Y-15	-70678.98	21910.91										
Y-16	-70682.32	21887.38										
Y-17	-70682.41	21886.71										
Y-18	-70684.88	21869.36										
Y-19	-70685.76	21863.17										
<del></del>												

平面直角座標系:第IX系(測地成果2011)

調査年度 令和5年度 様式5-5(2) 測量基準点の座標一覧 急傾斜地の位置 箇所番号 *I −141K2153−1* 箇所名 真里谷113 所在地 木更津市真里谷 備考 備考 地点記号 地点記号 X(m) Y(m) X(m) Y(m) Z(m) Z(m) T43 -70662.41 21936.78 42.02 T44 -70622.77 21941.44 40.07

千葉県

平面直角座標系:第IX系(測地成果2011)



真里谷113

所在地

様式5-5 危害のおそれのある土地の座標一覧

箇所番号

I -141K2153-2

箇所名

急傾斜地の位置

調査年度

木更津市真里谷

令和5年度

	危害のおそれ	このある区域の	の座標(土砂災	<b>纟害警戒区域</b>	)	著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)						
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	
Y-1	-70512.30	21958.85				R−1	-70508.12	21926.49				
Y-2	-70542.35	21948.14				R-2	-70524.82	21920.54				
Y-3	-70519.64	21912.39				R-3	-70519.64	21912.39				
Y-4	-70515.91	21906.51				R-4	-70515.91	21906.51				
Y-5	-70504.28	21883.04				R−5	-70507.76	21890.05				
Y-6	-70499.84	21874.08				R-6	-70502.08	21892.40				
Y-7	-70497.36	21875.33				R−7	-70497.56	21892.61				
Y-8	-70496.75	21875.48				R-8	-70498.16	21905.38				
Y-9	-70496.75	21875.49				R-9	-70497.31	21915.72				
Y-10	-70497.23	21885.47				R-10	-70496.49	21925.71				
Y-11	-70498.16	21905.38										
Y-12	-70497.31	21915.72										
Y-13	-70493.84	21957.94										

平面直角座標系:第IX系(測地成果2011)

様式5-5(2) 測量基準点の座標一覧

調査年度

急傾斜地の位置	箇所番号	I -1411	K2153-2	箇所名		真里谷113		所在地	木更津市真里	<del>谷</del>
地点記号	X(m)	Y(m)	Z(m)	借	考	地点記号	X(m)	Y(m)	Z(m)	備考
T52	-70559.12	21942.06	38.94	Dit.	,	76/WID-7	X(II)	1(11)	2(11)	να· · 3
T53	-70539.69	21944.58	38.50							
100	70000.00	21011.00	00.00							
	•									かた マエ ズ / YPU U.J P. T. 0.04.4.)
									半面直角座標系	: 第区系(測地成果2011)