


急傾斜地の崩壊区域調査

様式5-4 危害のおそれのある土地等の座標位置図



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度	令和5年度
千葉県花見川区幕張本郷1丁目、幕張本郷2丁目	

急傾斜地の位置	箇所番号	II-012K2070	箇所名	幕張本郷5	所在地
---------	------	-------------	-----	-------	-----

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-36861.06	18535.68	Y30	-36822.62	18512.33						
Y2	-36846.85	18539.42									
Y3	-36835.17	18540.69									
Y4	-36832.03	18532.31									
Y5	-36831.66	18531.33									
Y6	-36831.59	18531.14									
Y7	-36830.97	18529.48									
Y8	-36828.09	18521.77									
Y9	-36839.06	18518.21									
Y10	-36849.07	18515.47									
Y11	-36853.78	18521.75									
Y12	-36855.03	18523.41									
Y13	-36855.06	18523.47									
Y14	-36855.15	18523.65									
Y15	-36855.59	18524.55									
Y16	-36819.85	18503.87									
Y17	-36828.83	18499.10									
Y18	-36838.31	18494.21									
Y19	-36841.80	18502.71									
Y20	-36843.33	18506.42									
Y21	-36843.40	18506.60									
Y22	-36843.57	18507.01									
Y23	-36845.12	18509.50									
Y24	-36848.63	18515.12									
Y25	-36836.28	18519.59									
Y26	-36826.13	18523.06									
Y27	-36823.52	18515.08									
Y28	-36823.02	18513.56									
Y29	-36822.96	18513.37									

平面直角座標系: 第IX系(測地成果2011)