## 急傾斜地の崩壊区域調書

-4 危害のおそれのあ	の工地寺の座標位	直凶		T11.0			調査年度	2023
急傾斜地の位置	箇所番号	II −031K2059	箇所名	秋山6	所在地	松戸市秋山		
								N
								Λ
				Y8				
				/	9			
				Y7	~			
				V6 /				
				Y6 Y5 Y1 Y4 Y11	1			
				Y4 0	,			
				Y11				
				Y12				
			үз 🤇	// \				
			15	/ <sub>Y1</sub> \ Y13				
				Y2				
1:500								
10	20 m							

## 急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度 2023

				生記力		<i>4kulug</i>						
額料地の位置 箇所番号 II-031K2059		TK2059	箇所名 秋山6					所在地	松戸市秋山			
	危害のおそれのある区域の座標(土砂災害警戒区域)					著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)						
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	
Y1	-26202.68	8558.32										
Y2	-26210.34	8554.00										
Y3	-26205.12	8545.97										
Y4	-26198.43	8550.11										
Y5	-26196.61	8551.24										
Y6	-26195.34	8552.03										
Y7	-26191.37	8554.49										
Y8	-26186.84	8557.29										
Y9	-26191.61	8564.55										
Y10	-26197.39	8561.30										
Y11	-26200.32	8559.64										
Y12	-26201.63	8558.91										
Y13	-26202.68	8558.32										