
急傾斜地の崩壊区域調書



急傾斜地の崩壊区域調書

榎戸7

所在地

箇 所 名

II -053K2002

様式5-5 危害のおそれのある土地の座標一覧

急傾斜地の位置

|八街市榎戸、泉台2丁目、泉台1丁目、八街ろ

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-35604.255	41667.090				R1	-35607.413	41662.724			
Y2	-35585.271	41658.972				R2	-35589.632	41653.173			
Y3	-35567.371	41650.253				R3	-35572.477	41643.531			
Y4	-35551.006	41641.174				R4	-35556.592	41633.542			
Y5	-35551.006	41641.174				R5	-35556.592	41633.542			
Y6	-35538.197	41628.291				R6	-35560.338	41628.424			
Y7	-35521.558	41618.718				R7	-35560.338	41628.424			
Y8	-35510.101	41598.099				R8	-35563.127	41624.613			
Y9	-35515.911	41589.959				R9	-35563.127	41624.613			
Y10	-35516.846	41588.648				R10	-35578.228	41635.959			
Y11	-35520.440	41583.613				R11	-35594.413	41646.816			
Y12	-35521.260	41582.464				R12	-35610.137	41658.958			
Y13	-35523.864	41578.816				R13	-35610.127	41658.971			
Y14	-35524.621	41579.343									
Y15	-35541.209	41590.890									
Y16	-35559.034	41603.297									
Y17	-35575.954	41615.338									
Y18	-35598.769	41632.170									
Y19	-35614.385	41643.690									
Y20	-35618.816	41646.959									
Y21	-35614.952	41652.301									
Y22	-35614.865	41652.422									
Y23	-35610.127	41658.971									

平面直角座標系:第区系(測地成果2011)