


急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度 2024



急傾斜地の崩壊区域調査

様式5-5 危害のおそれのある土地等の座標一覧

調査年度

2024

急傾斜地の位置			箇所番号	II-061K2023-2	箇所名	伊能26	所在地	成田市伊能			
危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-16495.83	53932.21	Y-31	-16411.45	53918.86	R-1	-16473.95	53924.45			
Y-2	-16516.70	53917.63	Y-32	-16436.99	53952.53	R-2	-16494.58	53915.51			
Y-3	-16516.22	53915.59	Y-33	-16468.78	53951.18	R-3	-16514.74	53909.20			
Y-4	-16513.31	53903.02				R-4	-16513.31	53903.02			
Y-5	-16510.85	53892.40				R-5	-16512.49	53899.48			
Y-6	-16510.85	53892.40				R-6	-16493.12	53896.03			
Y-7	-16508.59	53882.66				R-7	-16479.85	53893.95			
Y-8	-16491.81	53878.55				R-8	-16469.86	53890.49			
Y-9	-16483.37	53875.77				R-9	-16465.28	53884.20			
Y-10	-16478.54	53874.12				R-10	-16461.70	53878.66			
Y-11	-16478.42	53874.35				R-11	-16459.53	53871.68			
Y-12	-16477.15	53872.94				R-12	-16460.86	53857.09			
Y-13	-16475.52	53869.84				R-13	-16464.30	53847.96			
Y-14	-16477.46	53858.89				R-14	-16473.98	53843.23			
Y-15	-16478.29	53857.00				R-15	-16481.56	53842.20			
Y-16	-16482.26	53857.97				R-16	-16495.63	53840.48			
Y-17	-16482.71	53858.46				R-17	-16514.01	53840.81			
Y-18	-16495.51	53856.56				R-18	-16515.13	53817.95			
Y-19	-16513.20	53857.15				R-19	-16515.48	53810.86			
Y-20	-16513.69	53847.17				R-20	-16515.64	53807.48			
Y-21	-16515.13	53817.95				R-21	-16495.87	53807.64			
Y-22	-16515.48	53810.86				R-22	-16479.18	53808.70			
Y-23	-16517.38	53772.05				R-23	-16456.52	53812.16			
Y-24	-16496.14	53771.63				R-24	-16435.08	53829.07			
Y-25	-16476.63	53772.73				R-25	-16429.01	53853.66			
Y-26	-16438.76	53780.56				R-26	-16429.53	53875.12			
Y-27	-16404.72	53809.44				R-27	-16432.30	53889.54			
Y-28	-16396.81	53850.18				R-28	-16438.65	53901.35			
Y-29	-16397.46	53878.79				R-29	-16452.58	53923.10			
Y-30	-16401.98	53900.76									

平面直角座標系:第Ⅸ系(測地成果2011)