

様式5-5 危害のおそれのある土地の座標一覧

調査年度

2024

急傾斜地の位置 | 箇所番号 | II-121K2077-1 | 箇所名 | 守谷24 | 所在地 | 勝浦市守谷

危害のおそれのある区域の座標(土砂災害警戒区域)					著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)						
地点記号	X(m)	Y(m)	地点記 号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-95849.76	39172.25	Y-31	-95849.79	39172.34	R−1	-95848.68	39169.38			
Y-2	-95849.13	39173.53	Y-32	-95849.76	39172.25	R-2	-95852.37	39171.36			
Y-3	-95829.37	39181.63				R-3	-95854.00	39169.36			
Y-4	-95828.25	39177.66				R-4	-95852.71	39166.22			
Y-5	-95829.34	39173.60				R-5	-95841.91	39166.38			
Y-6	-95830.49	39167.44				R-6	-95831.25	39152.21			
Y-7	-95830.98	39158.25				R-7	-95832.00	39140.17			
Y-8	-95830.22	39149.23				R-8	-95835.43	39134.82			
Y-9	-95830.15	39147.44				R-9	-95843.59	39129.17			
Y-10	-95830.48	39142.54				R-10	-95846.74	39128.51			
Y-11	-95835.43	39134.82				R-11	-95850.77	39134.10			
Y-12	-95843.59	39129.17				R-12	-95858.86	39136.72			
Y-13	-95846.74	39128.51				R-13	-95860.62	39137.02			
Y-14	-95850.77	39134.10				R-14	-95860.44	39140.54			
Y-15	-95858.86	39136.72				R-15	-95860.53	39142.39			
Y-16	-95860.62	39137.02				R-16	-95860.90	39144.80			
Y-17	-95860.44	39140.54				R-17	-95851.83	39141.84			
Y-18	-95860.53	39142.39				R-18	-95846.01	39137.71			
Y-19	-95861.07	39145.88				R-19	-95841.69	39139.09			
Y-20	-95861.33	39147.60				R-20	-95838.11	39145.18			
Y-21	-95867.42	39149.81				R-21	-95849.29	39157.42			
Y-22	-95873.60	39153.83				R-22	-95856.24	39159.01			
Y-23	-95876.49	39160.06				R-23	-95867.60	39164.66			
Y-24	-95878.53	39163.62				R-24	-95854.17	39175.66			
Y-25	-95862.12	39186.86				R-25	-95849.79	39172.34			
Y-26	-95851.54	39185.52				R-26	-95849.76	39172.25			
Y-27	-95851.54	39185.47				R-27	-95849.76	39172.25			
Y-28	-95851.96	39181.13				R-28	-95849.00	39170.23			1
Y-29	-95850.99	39175.62									
Y-30	-95850.96	39175.42									1

平面直角座標系:第区系(測地成果2011)

-4 危害のおそれの	ある土地等の座標係	立置図					調査年度	2024
急傾斜地の位置	箇所番号	II -121K2077-2	箇所名	守谷24	所在地	勝浦市守谷		
								Ņ
			/Y−2					
		Y-3		Y-1				
		•	Y-4					
				R-1 Y-	-16 -10			
					Y-15 R-9			
				/ >	R-8			
		Y-5		R-2 ♣	Y-14			
		10			Y-13			
				R −7				
				′ /		Y-12		
			Y-6 R-4			/		
			R-4 Y-7 R-5	R-6				
			R−5′	Y-8				
				Y-9		Y-11		
					V 10		凡 例	
					Y-10			
							害のおそれのある土地等 害のおそれのある土地の	
						I <u> </u> 厄	古いんてれいめる工地の	凸以
						Y-1 危	しい危害のおそれのある <u>-</u> 害のおそれのある土地の しい危害のおそれのある-	上地の区域 端点 地点記号

様式5-5 危害のおそれのある土地の座標一覧

調査年度

2024

急傾斜地の位置 | 箇所番号 | II-121K2077-2 | 箇所名 | 守谷24 | 所在地 | 勝浦市守谷

危害のおそれのある区域の座標(土砂災害警戒区域)					著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)						
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-95830.70	39163.46				R−1	-95833.56	39167.09			
Y-2	-95830.98	39158.25				R-2	-95837.99	39165.31			
Y-3	-95830.98	39158.23				R-3	-95844.45	39162.08			
Y-4	-95831.92	39158.13				R-4	-95844.80	39162.57			
Y-5	-95837.57	39152.47				R-5	-95845.14	39163.04			
Y-6	-95844.80	39162.57				R-6	-95845.45	39163.47			
Y-7	-95845.14	39163.04				R-7	-95840.37	39168.13			
Y-8	-95846.48	39164.91				R-8	-95836.29	39170.57			
Y-9	-95848.93	39168.32				R-9	-95835.58	39169.67			
Y-10	-95852.31	39173.04				R-10	-95835.47	39169.53			
Y-11	-95848.70	39177.99									
Y-12	-95844.23	39180.68									
Y-13	-95839.01	39174.04									
Y-14	-95838.05	39172.81									
Y-15	-95835.58	39169.67									
Y-16	-95835.47	39169.53									

平面直角座標系:第区系(測地成果2011)