


急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度 2024



急傾斜地の崩壊区域調査書

様式5-5 危害のおそれのある土地の座標一覧

調査年度

2024

急傾斜地の位置		箇所番号	II-121K2107-1		箇所名	松部44		所在地		勝浦市松部、吉尾	
危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-95356.42	41468.02				R-1	-95367.00	41476.78			
Y-2	-95356.17	41467.55				R-2	-95374.76	41463.74			
Y-3	-95349.42	41469.02				R-3	-95383.19	41461.68			
Y-4	-95342.26	41441.62				R-4	-95372.10	41449.58			
Y-5	-95361.97	41455.03				R-5	-95379.32	41445.69			
Y-6	-95361.97	41455.03				R-6	-95383.09	41443.66			
Y-7	-95379.32	41445.69				R-7	-95384.63	41442.58			
Y-8	-95383.09	41443.66				R-8	-95385.82	41441.01			
Y-9	-95384.63	41442.58				R-9	-95386.24	41440.11			
Y-10	-95385.82	41441.01				R-10	-95413.96	41454.99			
Y-11	-95387.94	41436.48				R-11	-95404.79	41484.18			
Y-12	-95387.94	41436.48				R-12	-95372.62	41481.44			
Y-13	-95392.19	41427.43				R-13	-95370.59	41479.75			
Y-14	-95425.32	41448.84									
Y-15	-95426.44	41451.32									
Y-16	-95427.77	41455.90									
Y-17	-95428.27	41456.92									
Y-18	-95424.61	41471.72									
Y-19	-95422.35	41474.67									
Y-20	-95418.92	41480.38									
Y-21	-95414.52	41487.18									
Y-22	-95413.89	41488.90									
Y-23	-95382.76	41489.83									
Y-24	-95381.39	41488.70									
Y-25	-95375.05	41483.45									
Y-26	-95370.59	41479.75									
Y-27	-95363.66	41474.02									


平面直角座標系：第Ⅸ区(測地成果2011)

平面直角座標系：第Ⅸ系(測地成果2011)

急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度 2024



急傾斜地の崩壊区域調査書

様式5-5 危害のおそれのある土地の座標一覧

調査年度

2024

急傾斜地の位置	箇所番号	II-121K2107-2		箇所名	松部44		所在地	勝浦市松部、吉尾			
危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-95363.72	41516.80				R-1	-95383.54	41518.49			
Y-2	-95367.52	41518.35				R-2	-95385.01	41509.50			
Y-3	-95370.50	41524.73				R-3	-95382.67	41509.96			
Y-4	-95376.16	41517.86				R-4	-95379.01	41505.29			
Y-5	-95376.16	41517.86				R-5	-95381.05	41502.01			
Y-6	-95377.71	41518.00				R-6	-95381.53	41501.24			
Y-7	-95391.61	41519.19				R-7	-95395.39	41495.63			
Y-8	-95404.04	41520.25				R-8	-95400.19	41501.81			
Y-9	-95410.20	41520.78				R-9	-95399.60	41519.87			
Y-10	-95414.01	41521.11				R-10	-95391.61	41519.19			
Y-11	-95413.93	41518.05									
Y-12	-95412.78	41500.47									
Y-13	-95411.57	41493.10									
Y-14	-95411.59	41492.15									
Y-15	-95409.56	41488.76									
Y-16	-95409.31	41488.74									
Y-17	-95400.43	41491.16									
Y-18	-95393.16	41492.47									
Y-19	-95386.40	41493.38									
Y-20	-95386.37	41493.43									
Y-21	-95385.10	41495.47									
Y-22	-95381.53	41501.24									
Y-23	-95381.05	41502.01									
Y-24	-95376.26	41509.74									
Y-25	-95374.26	41514.94									
Y-26	-95369.60	41517.30									
Y-27	-95369.60	41517.30									


平面直角座標系：第Ⅸ区(測地成果2011)

平面直角座標系：第Ⅸ系(測地成果2011)

急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度 2024



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度

2024

[illegible]

平面直角座標系：第Ⅸ系(測地成果2011)