

桑田3

様式5-5 危害のおそれのある土地の座標一覧

箇所番号

II −122K2109−1

箇所名

急傾斜地の位置


調査年度

平面直角座標系:第IX系(測地成果2011)

所在地 いすみ市岬町桑田、岩熊

2024

| 危害のおそれのある区域の座標(土砂災害警戒区域) | | | | | | 著しい危害のおそれのある区域の座標(土砂災害特別警戒区域) | | | | | | |
|--------------------------|-----------|----------|------|------|------|-------------------------------|-----------|----------|------|------|-----|--|
| 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m | |
| Y-1 | -76374.80 | 46345.48 | | | | R−1 | -76374.38 | 46317.29 | | | | |
| Y-2 | -76343.74 | 46350.72 | | | | R−2 | -76356.72 | 46320.12 | | | | |
| Y-3 | -76336.98 | 46345.14 | | | | R-3 | -76346.79 | 46312.90 | | | | |
| Y-4 | -76313.69 | 46348.86 | | | | R-4 | -76326.19 | 46311.81 | | | | |
| Y-5 | -76307.21 | 46305.53 | | | | R−5 | -76308.82 | 46300.42 | | | | |
| Y-6 | -76307.89 | 46303.37 | | | | R-6 | -76310.22 | 46296.00 | | | | |
| Y-7 | -76310.22 | 46296.00 | | | | R−7 | -76339.45 | 46277.66 | | | | |
| Y-8 | -76311.97 | 46290.46 | | | | R-8 | -76355.56 | 46284.07 | | | | |
| Y-9 | -76312.57 | 46288.56 | | | | R-9 | -76366.32 | 46289.90 | | | | |
| Y-10 | -76314.98 | 46280.93 | | | | R−10 | -76373.96 | 46288.62 | | | | |
| Y-11 | -76348.00 | 46267.28 | | | | R-11 | -76374.24 | 46307.38 | | | | |
| Y-12 | -76348.65 | 46269.14 | | | | | | | | | | |
| Y-13 | -76352.65 | 46271.45 | | | | | | | | | | |
| Y-14 | -76362.84 | 46272.50 | | | | | | | | | | |
| Y−15 | -76365.93 | 46273.80 | | | | | | | | | | |
| Y-16 | -76368.03 | 46277.15 | | | | | | | | | | |
| Y-17 | -76373.79 | 46277.29 | | | | | | | | | | |
| Y-18 | -76373.86 | 46281.94 | | | | | | | | | | |
| Y-19 | -76374.24 | 46307.38 | | | | | | | | | | |
| Y-20 | -76374.58 | 46330.56 | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |



桑田3

様式5-5 危害のおそれのある土地の座標一覧

箇所番号

II -122K2109-2

箇所名

急傾斜地の位置

調査年度

平面直角座標系:第IX系(測地成果2011)

所在地 いすみ市岬町桑田、岩熊

2024

| 危害のおそれのある区域の座標(土砂災害警戒区域) | | | | | | | | | T | | |
|--------------------------|--------------|----------|------|------|--------------|------|-----------|----------|------|------|--|
| 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m |
| Y−1 | -76292.89 | 46304.45 | | | | R−1 | -76281.99 | 46288.09 | | | |
| Y-2 | -76266.83 | 46316.05 | | | | R−2 | -76268.46 | 46294.29 | | | |
| Y-3 | -76251.05 | 46316.13 | | | | R-3 | -76253.23 | 46292.84 | | | |
| Y-4 | -76230.44 | 46312.07 | | | | R−4 | -76238.11 | 46291.69 | | | |
| Y−5 | -76238.63 | 46290.29 | | | | R-5 | -76238.63 | 46290.29 | | | |
| Y-6 | -76241.37 | 46283.02 | | | | R-6 | -76241.37 | 46283.02 | | | |
| Y-7 | -76245.27 | 46272.64 | | | | R−7 | -76245.27 | 46272.64 | | | |
| Y-8 | -76248.90 | 46266.72 | | | | R-8 | -76245.87 | 46271.67 | | | |
| Y-9 | -76253.27 | 46259.58 | | | | R-9 | -76256.04 | 46272.82 | | | |
| Y-10 | -76254.12 | 46258.19 | | | | R-10 | -76265.98 | 46271.94 | | | |
| Y-11 | -76256.74 | 46260.31 | | | | R−11 | -76269.17 | 46268.87 | | | |
| Y-12 | -76259.98 | 46255.09 | | | | R-12 | -76277.36 | 46281.16 | | | |
| Y-13 | -76264.03 | 46261.17 | | | | | | | | | |
| Y-14 | -76264.61 | 46262.04 | | | | | | | | | |
| Y-15 | -76277.36 | 46281.16 | | | | | | | | | |
| Y-16 | -76287.85 | 46296.89 | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | 1 | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | 1 | | | | | | |
| | | | | | | 1 | | | | | |
| | 1 | | ╟──┤ | | | 1 | | | | | |
| | | | | | | | | | | | |
| | | | | | | 1 | | | | | |