


急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度

令和4年度



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度 令和4年度

急傾斜地の位置			箇所番号		II-124K2008		箇所名		岩和田45		所在地		夷隅郡御宿町岩和田	
危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)								
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-90208.02	48602.56	Y-32	-90173.94	48592.70	R-1	-90212.99	48585.13						
Y-2	-90212.40	48587.21	Y-33	-90186.33	48595.83	R-2	-90215.34	48576.88						
Y-3	-90215.34	48576.88	Y-34	-90193.49	48595.97	R-3	-90216.46	48572.96						
Y-4	-90216.46	48572.96				R-4	-90217.93	48568.17						
Y-5	-90219.52	48562.97				R-5	-90209.66	48562.58						
Y-6	-90220.82	48558.75				R-6	-90192.97	48560.83						
Y-7	-90222.46	48553.41				R-7	-90184.45	48559.25						
Y-8	-90221.43	48552.36				R-8	-90176.34	48553.79						
Y-9	-90220.22	48552.19				R-9	-90172.16	48550.43						
Y-10	-90217.17	48551.23				R-10	-90163.34	48547.08						
Y-11	-90215.61	48550.28				R-11	-90156.16	48539.08						
Y-12	-90212.91	48548.63				R-12	-90144.18	48527.23						
Y-13	-90211.90	48547.28				R-13	-90143.11	48526.54						
Y-14	-90195.78	48545.98				R-14	-90139.86	48529.56						
Y-15	-90191.76	48546.39				R-15	-90141.08	48530.20						
Y-16	-90184.79	48541.13				R-16	-90153.03	48542.23						
Y-17	-90179.21	48535.66				R-17	-90159.65	48556.30						
Y-18	-90169.27	48532.29				R-18	-90167.29	48563.27						
Y-19	-90166.46	48528.70				R-19	-90172.80	48565.37						
Y-20	-90154.94	48516.92				R-20	-90179.32	48574.77						
Y-21	-90154.22	48516.18				R-21	-90189.78	48577.65						
Y-22	-90151.70	48518.53				R-22	-90201.20	48580.05						
Y-23	-90146.91	48522.99												
Y-24	-90143.11	48526.54												
Y-25	-90136.57	48532.62												
Y-26	-90135.79	48533.35												
Y-27	-90136.96	48534.15												
Y-28	-90148.71	48546.59												
Y-29	-90156.22	48564.88												
Y-30	-90163.14	48574.79												
Y-31	-90169.47	48577.10												