

急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度

2023

急傾斜地の位置

箇所番号


II-131K2148-1

箇所名

沼12

所在地

館山市沼、宮城



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度	2023
------	------

急傾斜地の位置	箇所番号	II-131K2148-1	箇所名	沼12	所在地	館山市沼、宮城
---------	------	---------------	-----	-----	-----	---------

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-114443.28	1148.29	Y31	-114468.72	1222.49	R1	-114445.74	1260.58			
Y2	-114432.08	1149.98	Y32	-114466.73	1210.03	R2	-114450.59	1265.63			
Y3	-114426.05	1153.23	Y33	-114465.13	1196.03	R3	-114450.03	1260.33			
Y4	-114419.06	1155.72	Y34	-114463.34	1180.40	R4	-114451.16	1259.34			
Y5	-114414.35	1156.88	Y35	-114460.00	1151.14	R5	-114452.34	1258.39			
Y6	-114408.53	1157.68	Y36	-114458.56	1150.89	R6	-114455.62	1256.36			
Y7	-114405.89	1157.94	Y37	-114456.71	1149.77	R7	-114464.02	1248.11			
Y8	-114400.89	1158.01	Y38	-114454.79	1147.65	R8	-114472.27	1241.84			
Y9	-114398.04	1157.82	Y39	-114453.41	1146.11	R9	-114468.72	1222.49			
Y10	-114393.50	1159.75	Y40	-114443.28	1148.29	R10	-114466.73	1210.03			
Y11	-114384.98	1172.59				R11	-114465.13	1196.03			
Y12	-114379.61	1199.06				R12	-114463.80	1184.37			
Y13	-114382.39	1201.66				R13	-114455.83	1184.36			
Y14	-114416.11	1233.24				R14	-114444.54	1186.84			
Y15	-114431.86	1247.98				R15	-114421.87	1189.80			
Y16	-114440.55	1255.71				R16	-114413.09	1193.32			
Y17	-114445.74	1260.58				R17	-114407.47	1204.37			
Y18	-114450.82	1265.87				R18	-114408.05	1225.69			
Y19	-114454.37	1270.74				R19	-114416.11	1233.24			
Y20	-114454.71	1271.32				R20	-114431.86	1247.98			
Y21	-114457.86	1276.61				R21	-114440.55	1255.71			
Y22	-114459.82	1279.91				R22	-114445.74	1260.58			
Y23	-114458.78	1275.14									
Y24	-114459.63	1274.24									
Y25	-114460.32	1273.41									
Y26	-114461.99	1271.74									
Y27	-114468.06	1263.64									
Y28	-114475.02	1256.89									
Y29	-114474.56	1254.37									
Y30	-114473.22	1247.06									

平面直角座標系：第Ⅸ系(測地成果2011)

急傾斜地の崩壊区域調査

様式5-4 危害のおそれのある土地等の座標位置図

調査年度

2023

急傾斜地の位置

箇所番号


II-131K2148-2

箇所名

沼12

所在地

館山市沼、宮城



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度	2023
------	------

[illegible]

平面直角座標系:第Ⅳ系(測地成果2011)

千葉県