

急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度

2024

急傾斜地の位置

箇所番号


II-132K2348-2

箇所名

内浦34

所在地

鴨川市内浦



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度	2024
鴨川市内浦	

急傾斜地の位置	箇所番号	II-132K2348-2	箇所名	内浦34		所在地	鴨川市内浦				
危害のおそれのある区域の座標						著しい危害のおそれのある区域の座標					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-96697.46	34176.70	Y31	-96735.37	34280.58	R1	-96693.85	34187.66			
Y2	-96698.61	34176.84	Y32	-96725.97	34275.44	R2	-96706.60	34194.40			
Y3	-96701.06	34176.84	Y33	-96711.05	34273.75	R3	-96717.53	34192.34			
Y4	-96703.40	34176.61	Y34	-96709.13	34273.23	R4	-96724.32	34194.17			
Y5	-96705.19	34176.05	Y35	-96700.36	34271.49	R5	-96730.31	34187.12			
Y6	-96706.35	34175.49	Y36	-96696.53	34270.73	R6	-96739.16	34193.74			
Y7	-96707.60	34174.30	Y37	-96696.43	34270.68	R7	-96747.23	34199.77			
Y8	-96708.73	34172.31	Y38	-96695.05	34269.94	R8	-96760.11	34208.85			
Y9	-96709.65	34170.11	Y39	-96692.83	34266.97	R9	-96737.35	34265.53			
Y10	-96710.41	34172.26	Y40	-96692.43	34266.12	R10	-96736.31	34265.68			
Y11	-96718.34	34178.18	Y41	-96688.49	34257.66	R11	-96716.39	34265.64			
Y12	-96739.16	34193.74	Y42	-96684.26	34243.79	R12	-96689.82	34260.50			
Y13	-96747.23	34199.77	Y43	-96682.46	34232.68	R13	-96688.49	34257.66			
Y14	-96764.33	34211.82	Y44	-96682.14	34224.32	R14	-96684.26	34243.79			
Y15	-96764.80	34212.15	Y45	-96683.73	34218.39	R15	-96682.46	34232.68			
Y16	-96765.54	34213.84	Y46	-96690.20	34198.76	R16	-96682.14	34224.32			
Y17	-96765.63	34215.46	Y47	-96695.48	34182.73	R17	-96683.73	34218.39			
Y18	-96765.34	34217.08				R18	-96690.20	34198.76			
Y19	-96764.78	34220.12									
Y20	-96760.49	34225.66									
Y21	-96757.01	34230.17									
Y22	-96754.07	34233.97									
Y23	-96751.62	34237.16									
Y24	-96749.60	34239.77									
Y25	-96748.35	34242.24									
Y26	-96747.04	34244.82									
Y27	-96743.48	34251.85									
Y28	-96740.77	34260.59									
Y29	-96735.89	34280.19									
Y30	-96735.70	34280.58									

平面直角座標系：第Ⅸ系(測地成果2011)