

急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度

2024

急傾斜地の位置

箇所番号


II-132K2358-1

箇所名

内浦40

所在地

鴨川市内浦



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度	2024
所在地	鴨川市内浦

急傾斜地の位置	箇所番号	II-132K2358-1	箇所名	内浦40		所在地	鴨川市内浦				
危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-94652.52	33157.17	Y30	-94601.21	33054.48	R1	-94658.39	33150.06	R30	-94597.55	33030.96
Y2	-94650.40	33155.27	Y31	-94600.91	33050.37	R2	-94647.11	33152.21	R31	-94597.05	33029.84
Y3	-94648.32	33153.62	Y32	-94600.52	33044.88	R3	-94646.17	33152.03	R32	-94595.93	33027.35
Y4	-94643.02	33149.70	Y33	-94599.99	33041.26	R4	-94643.02	33149.70	R33	-94594.16	33024.39
Y5	-94632.72	33142.63	Y34	-94599.76	33039.33	R5	-94632.72	33142.63	R34	-94592.10	33021.77
Y6	-94627.26	33138.38	Y35	-94599.48	33038.16	R6	-94627.26	33138.38	R35	-94589.42	33019.06
Y7	-94622.93	33133.91	Y36	-94598.66	33034.31	R7	-94622.93	33133.91	R36	-94586.19	33016.40
Y8	-94618.01	33126.65	Y37	-94597.55	33030.96	R8	-94618.01	33126.65	R37	-94583.22	33014.36
Y9	-94615.46	33121.68	Y38	-94597.05	33029.84	R9	-94615.46	33121.68	R38	-94578.55	33011.72
Y10	-94613.55	33116.92	Y39	-94595.93	33027.35	R10	-94613.55	33116.92	R39	-94575.98	33010.27
Y11	-94611.47	33110.64	Y40	-94594.16	33024.39	R11	-94611.47	33110.64	R40	-94571.49	33008.37
Y12	-94614.73	33109.67	Y41	-94592.10	33021.77	R12	-94614.73	33109.67	R41	-94566.37	33006.65
Y13	-94628.54	33105.57	Y42	-94589.42	33019.06	R13	-94623.28	33107.13	R42	-94562.05	33005.67
Y14	-94630.63	33104.95	Y43	-94586.19	33016.40	R14	-94626.71	33117.71	R43	-94562.13	33005.06
Y15	-94638.13	33102.72	Y44	-94583.22	33014.36	R15	-94635.82	33131.84	R44	-94562.52	33002.19
Y16	-94640.68	33111.65	Y45	-94578.55	33011.72	R16	-94651.50	33138.46	R45	-94563.03	32998.75
Y17	-94644.20	33118.92	Y46	-94575.98	33010.27	R17	-94665.98	33140.87	R46	-94564.60	32993.99
Y18	-94657.35	33121.66	Y47	-94571.49	33008.37	R18	-94662.84	33144.67	R47	-94564.63	32993.80
Y19	-94673.50	33128.44	Y48	-94566.37	33006.65				R48	-94575.17	32997.80
Y20	-94672.70	33129.87	Y49	-94562.05	33005.67	R19	-94602.64	33073.50	R49	-94583.60	33000.63
Y21	-94668.60	33137.16	Y50	-94562.13	33005.06	R20	-94602.61	33073.32	R50	-94594.62	33013.10
Y22	-94667.65	33138.85	Y51	-94562.52	33002.19	R21	-94602.43	33071.89	R51	-94606.17	33023.62
Y23	-94662.84	33144.67	Y52	-94563.03	32998.75	R22	-94601.82	33064.22	R52	-94610.98	33034.46
Y24	-94656.37	33152.51	Y53	-94564.60	32993.99	R23	-94601.57	33061.11	R53	-94613.68	33049.93
			Y54	-94564.93	32992.39	R24	-94601.21	33054.48	R54	-94615.65	33070.46
Y25	-94602.64	33073.50	Y55	-94565.18	32989.75	R25	-94600.91	33050.37	R55	-94605.76	33072.77
Y26	-94602.61	33073.32	Y56	-94566.15	32979.79	R26	-94600.64	33046.55			
Y27	-94602.43	33071.89	Y57	-94579.71	32984.75	R27	-94601.15	33038.72			
Y28	-94601.82	33064.22	Y58	-94587.88	32987.04	R28	-94599.48	33038.16			
Y29	-94601.57	33061.11	Y59	-94603.33	33003.14	R29	-94598.66	33034.31			
						平面直角座標系：第Ⅸ区系(測地成果2011)					

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度	2024
------	------

急傾斜地の位置	箇所番号	II-132K2358-1	箇所名	内浦40	所在地	鴨川市内浦
---------	------	---------------	-----	------	-----	-------

[illegible]

平面直角座標系:第Ⅸ系(測地成果2011)