


急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

| | |
|------|-------|
| 調査年度 | 令和5年度 |
|------|-------|



急傾斜地の崩壊区域調査

様式5-5 危害のおそれのある土地の座標一覧

調査年度 令和5年度

急傾斜地の位置 箇所番号 II-141K2045 箇所名 茅野七曲18 所在地 木更津市茅野七曲

| 危害のおそれのある区域の座標(土砂災害警戒区域) | | | | | | 著しい危害のおそれのある区域の座標(土砂災害特別警戒区域) | | | | | |
|--------------------------|-----------|----------|------|-----------|----------|-------------------------------|-----------|----------|------|------|------|
| 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) |
| Y-1 | -72762.10 | 23611.36 | Y-31 | -72773.37 | 23587.09 | R-1 | -72804.54 | 23666.43 | | | |
| Y-2 | -72761.86 | 23624.91 | Y-32 | -72765.06 | 23604.05 | R-2 | -72803.58 | 23658.04 | | | |
| Y-3 | -72754.39 | 23645.25 | | | | R-3 | -72807.17 | 23644.81 | | | |
| Y-4 | -72753.57 | 23650.87 | | | | R-4 | -72814.79 | 23630.21 | | | |
| Y-5 | -72752.04 | 23671.38 | | | | R-5 | -72822.59 | 23616.14 | | | |
| Y-6 | -72752.24 | 23677.75 | | | | R-6 | -72828.79 | 23608.80 | | | |
| Y-7 | -72782.93 | 23673.23 | | | | R-7 | -72834.40 | 23605.07 | | | |
| Y-8 | -72786.18 | 23672.76 | | | | R-8 | -72884.32 | 23634.10 | | | |
| Y-9 | -72793.28 | 23671.71 | | | | R-9 | -72873.28 | 23626.35 | | | |
| Y-10 | -72811.85 | 23663.01 | | | | R-10 | -72867.85 | 23622.16 | | | |
| Y-11 | -72815.51 | 23661.29 | | | | R-11 | -72864.23 | 23618.89 | | | |
| Y-12 | -72820.91 | 23658.76 | | | | R-12 | -72860.20 | 23613.85 | | | |
| Y-13 | -72819.56 | 23656.02 | | | | R-13 | -72855.34 | 23608.13 | | | |
| Y-14 | -72821.44 | 23651.07 | | | | R-14 | -72847.83 | 23599.29 | | | |
| Y-15 | -72828.72 | 23637.54 | | | | R-15 | -72817.06 | 23581.44 | | | |
| Y-16 | -72836.13 | 23624.12 | | | | R-16 | -72806.97 | 23592.75 | | | |
| Y-17 | -72839.06 | 23620.67 | | | | R-17 | -72799.11 | 23602.28 | | | |
| Y-18 | -72840.42 | 23620.39 | | | | R-18 | -72790.98 | 23617.69 | | | |
| Y-19 | -72897.98 | 23641.37 | | | | R-19 | -72783.48 | 23634.41 | | | |
| Y-20 | -72897.88 | 23641.32 | | | | R-20 | -72777.72 | 23655.29 | | | |
| Y-21 | -72889.15 | 23636.67 | | | | R-21 | -72777.27 | 23674.07 | | | |
| Y-22 | -72884.32 | 23634.10 | | | | R-22 | -72782.93 | 23673.23 | | | |
| Y-23 | -72873.28 | 23626.35 | | | | R-23 | -72786.18 | 23672.76 | | | |
| Y-24 | -72867.85 | 23622.16 | | | | R-24 | -72793.28 | 23671.71 | | | |
| Y-25 | -72864.23 | 23618.89 | | | | | | | | | |
| Y-26 | -72860.20 | 23613.85 | | | | | | | | | |
| Y-27 | -72855.34 | 23608.13 | | | | | | | | | |
| Y-28 | -72822.97 | 23570.02 | | | | | | | | | |
| Y-29 | -72797.90 | 23558.48 | | | | | | | | | |
| Y-30 | -72782.04 | 23576.28 | | | | | | | | | |

平面直角座標系：第IX系(測地成果2011)

