
急傾斜地の崩壊区域調書



急傾斜地の崩壊区域調書

真里谷117

所在地

様式5-5 危害のおそれのある土地の座標一覧

箇所番号

II −141K2149

箇所名

急傾斜地の位置

調査年度

木更津市真里谷

令和5年度

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)						
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	
Y-1	-71106.50	22783.21				R−1	-71101.08	22808.39				
Y-2	-71088.46	22775.06				R−2	-71085.63	22803.38				
Y-3	-71088.01	22779.58				R-3	-71084.65	22813.27				
Y-4	-71084.65	22813.27				R−4	-71083.88	22820.98				
Y-5	-71083.88	22820.98				R-5	-71083.91	22827.86				
Y-6	-71083.91	22827.86				R-6	-71084.37	22832.02				
Y-7	-71085.11	22838.61				R−7	-71094.08	22834.10				
Y-8	-71085.63	22843.24				R-8	-71097.07	22827.06				
Y-9	-71086.22	22848.55				R-9	-71099.04	22817.86				
Y-10	-71087.54	22849.48										
Y-11	-71089.89	22843.94										
Y-12	-71091.45	22840.28										
Y-13	-71097.07	22827.06										
Y-14	-71099.04	22817.86										

平面直角座標系:第IX系(測地成果2011)

急傾斜地の崩壊区域調書

様式5-5(2) 測量基準点の座標一覧

頃斜地の位置	箇所番号	II -141K2149		箇所名		真里谷117		所在地	木更津市真島	<i>里谷</i>	13 7 110 1 2
										-	
地点記号	X(m)	Y(m) Z(m) 備考		考	地点記号	X(m)	Y(m)	Z(m)	備考		
T60	-70994.19	22767.11	41.79								
T61	-71022.84	22743.63	42.32								
			<u> </u>								