急傾斜地の崩壊区域調書

| | | 心気が | 地切朋场区均 | ~ II/- II | | | |
|-----------------------------------|--------------|--|--|---|--------------|--------------------------------------|--|
| 様式5-4 危害のおそれのある土地等の座標位 | は 置図 | | | | | 調査年度 | 令和5年度 |
| 急傾斜地の位置 箇所番号 | II -141K2181 | 箇所名 | 真里谷130 | 所在地 | 木更津市真里 | 公 | |
| 10.17.0.1.0.0.1 E.17. E.17. E.17. | | | | 171 = -0 | | | |
| | | | | | ////// | /// / | N |
| †° | | 100 | WIX | | //// | | 17 |
| | | VIH (| | | /// | //// | 1 |
| J | | | | | /// | 11/_ | |
| | | | | | | | |
| | | V-9/ | | | | | |
| | 1/1 | Y-37 | | | | | |
| | | 100 | | | | | |
| | | R-P | | | | 117111 | |
| | | R-4 | R/8 12 13 | | | 111111 | |
| | 1 | | Provide All Provided All Provid | | | | |
| | | Y-8+ | R-10 | | | 1/ \ | |
| | | Y-4- | 1700 | | | IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII | |
| // | 1/1/ | R-3 | R/11- Y-14 | 1 | 1 | | 1 |
| // | 11/6/ | ///// | Y-15 | | 1 | | |
| _//\ | 11/11/10 | Y-3 R 2 | N-16 | | 1 | //////// | |
| 7 | UMM | | | | | //// } | <i>J.</i> |
| 77 | 1 111 | The state of the s | 1 / 1 | | | | |
| | 1 (H) | 1 v-d. | | | | | |
| | | 11-11-1 | | -7/// | | | |
| | // 5)) | Y-1 | | 7////// | | | |
| | | //// | ((| 1111111 | | | |
| | | | | HHHHH | 11// | | |
| | | 1/1/2 1 | | HHHHH | 1111 | | James Comments of the Comments |
| | | | | 71 | | | / / |
| | 1 | | | 111111 | 11111 | | <i></i> |
| | 1 | 1//// | T89— | 3////////////////////////////////////// | 11111 | | 4 |
| | | 1 / 11/11 | | 3/////// | 11 1 1 1 / / | | |
| | | 1//// | | 20/1/// | (/ / | | |
| | /// | //h | | | | | 1 1 |
| | 1/17 | | all | 111111 | 1111 / / | | 1.1 |
| | | (1)1 | | | | | |
| | | 1/1/ | X /// | | | | |
| | II/I | 1 // // | 111 | | 1// | | |
| | | - 11/1 W | | | /// > | | 1:1,500 |
| | | 1)11/2 | Ton | | | -1111111 | 1.1,000 |
| | | 1 (1 / /// | ▼ 88 | | | | 111 |
| | | Carlotte Million | N | | 0 | 50 | 100 m |
| | | | | 1 44 L | | | 1 1 3 1 |
| 42 | -1v-1201 | 1 7 E 2 34(1) | 11 11 A | 0.118 | A SIMI | | 94 94 93 93 |

急傾斜地の崩壊区域調書

真里谷130

所在地

様式5-5 危害のおそれのある土地の座標一覧

箇所番号

II −141K2181

箇所名

急傾斜地の位置

調査年度

木更津市真里谷

令和5年度

| | T | 1 | の座標(土砂災 | | T | - | | 1 | の座標(土砂) | | T |
|----------|-----------|----------|----------|------|------|----------|-----------|----------|---------|------|------|
| 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) |
| Y-1 | -69486.88 | 22175.81 | | | | R−1 | -69468.17 | 22171.95 | | | |
| Y-2 | -69478.53 | 22174.09 | | | | R−2 | -69459.64 | 22170.19 | | | |
| Y-3 | -69459.64 | 22170.19 | ļ | | | R−3 | -69450.27 | 22168.25 | | | |
| Y-4 | -69445.01 | 22167.17 | | | | R-4 | -69427.10 | 22176.84 | | | |
| Y-5 | -69435.22 | 22165.14 | | | | R−5 | -69423.95 | 22191.24 | | | |
| Y-6 | -69412.65 | 22168.83 | | | | R−6 | -69417.26 | 22189.76 | | | |
| Y-7 | -69410.50 | 22180.51 | | | | R−7 | -69420.01 | 22193.32 | | | |
| Y-8 | -69406.99 | 22176.48 | | | | R-8 | -69425.97 | 22200.05 | | | |
| Y-9 | -69411.61 | 22182.46 | | | | R-9 | -69427.75 | 22201.38 | | | |
| Y-10 | -69413.11 | 22184.39 | | | | R−10 | -69435.33 | 22207.03 | | | |
| Y-11 | -69420.01 | 22193.32 | | | | R-11 | -69445.59 | 22204.04 | | | |
| Y-12 | -69425.97 | 22200.05 | | | | R−12 | -69454.90 | 22192.25 | | | |
| Y-13 | -69427.75 | 22201.38 | | | | | | | | | |
| Y-14 | -69450.16 | 22218.08 | | | | | | | | | |
| Y−15 | -69454.34 | 22221.19 | | | | | | | | | |
| Y-16 | -69465.22 | 22215.65 | | | | | | | | | |
| Y-17 -69 | -69483.46 | 22208.09 | 1 | | | 1 | | | | | |
| | | | | | | | | | | | |
| | | | | | | 1 | | | | | |
| | | | | | | 1 | | | | | |
| | | | | | | 1 | | | | | |
| | | | | | | 1 | | | | | |
| | | | 1 | | | 1 | | | | | |
| | | | 1 | | | 1 | | | | | |
| | | | 1 | | | 1 | | | | | |
| | | | 1 | | | 1 | | | | | |
| | | | 1 | | | 1 | | | | | |
| | | | 1 | | | 1 | <u> </u> | | | | |
| | | | - | | | - | | | | | |
| | | | | | | _ | | | | | |

急傾斜地の崩壊区域調書

調査年度 令和5年度 様式5-5(2) 測量基準点の座標一覧 急傾斜地の位置 箇所番号 *II −141K2181* 箇所名 真里谷130 所在地 木更津市真里谷 備考 備考 地点記号 地点記号 X(m) Y(m) Z(m) X(m) Y(m) Z(m) T88 -69583.32 22209.09 40.27 T89 -69527.13 22198.44 43.00

平面直角座標系:第IX系(測地成果2011)