

急傾斜地の崩壊区域調査

様式5-4 危害のおそれのある土地等の座標位置図

調査年度

2024

急傾斜地の位置

箇所番号


Ⅱ-143K2099

箇所名

金谷49

所在地

富津市金谷、安房郡鋸南町元名



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度	2024
所在地	富津市金谷、安房郡鋸南町元名

急傾斜地の位置	箇所番号	Ⅱ-143K2099	箇所名	金谷49	所在地	富津市金谷、安房郡鋸南町元名					
危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-93262.66	-312.74				R-1	-93303.00	-323.33			
Y-2	-93253.26	-336.52				R-2	-93294.73	-341.48			
Y-3	-93229.59	-361.73				R-3	-93270.58	-358.78			
Y-4	-93166.86	-480.22				R-4	-93198.46	-458.75			
Y-5	-93177.56	-491.74				R-5	-93209.51	-470.57			
Y-6	-93233.67	-484.52				R-6	-93265.69	-460.95			
Y-7	-93215.11	-517.02				R-7	-93246.17	-494.11			
Y-8	-93208.91	-536.48				R-8	-93239.29	-513.22			
Y-9	-93213.76	-543.11				R-9	-93243.89	-519.52			
Y-10	-93221.76	-556.71				R-10	-93251.74	-533.23			
Y-11	-93261.12	-525.88				R-11	-93261.12	-525.88			
Y-12	-93377.32	-434.87				R-12	-93373.13	-438.16			
Y-13	-93383.80	-429.79				R-13	-93356.18	-431.55			
Y-14	-93385.19	-428.70				R-14	-93352.86	-426.22			
Y-15	-93367.75	-422.49				R-15	-93347.43	-419.40			
Y-16	-93364.51	-417.30				R-16	-93337.59	-408.01			
Y-17	-93358.92	-410.93				R-17	-93328.25	-391.90			
Y-18	-93348.42	-400.03				R-18	-93322.00	-374.81			
Y-19	-93340.42	-383.84				R-19	-93321.65	-355.10			
Y-20	-93334.27	-366.47				R-20	-93324.31	-345.01			
Y-21	-93334.52	-354.17				R-21	-93327.64	-329.79			
Y-22	-93336.16	-346.43				R-22	-93311.02	-325.43			
Y-23	-93338.88	-332.74									
Y-24	-93332.18	-330.99									
Y-25	-93329.20	-330.21									
Y-26	-93311.02	-325.43									

平面直角座標系:第Ⅸ系(測地成果2011)

平面直角座標系：第Ⅸ区系(測地成果2011)