
急傾斜地の崩壊区域調書



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧 調査年度 *平成29年度* 急傾斜地の位置 箇所番号 *II-7028* 箇所 名 逆井2 所在地 柏市逆井

| 危害のおそれのある区域の座標(土砂災害警戒区域) | | | | | | 著しい危害のおそれのある区域の座標(土砂災害特別警戒区域) | | | | | |
|--------------------------|-----------|----------|------------------|------|------|-------------------------------|-----------|----------|------|------|------|
| 地点記号 | X(m) | Y(m) | 地点記 号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) |
| Y−1 | -20741.73 | 12754.81 | | | | R−1 | -20733.94 | 12755.12 | | | |
| Y-2 | -20722.08 | 12782.01 | | | | R-2 | -20717.30 | 12777.35 | | | |
| Y-3 | -20709.40 | 12793.23 | | | | R-3 | -20705.01 | 12788.60 | | | |
| Y-4 | -20702.98 | 12798.11 | | | | R-4 | -20696.62 | 12796.19 | | | |
| Y−5 | -20704.22 | 12810.61 | | | | R-5 | -20698.65 | 12807.96 | | | |
| Y-6 | -20688.06 | 12825.95 | | | | R-6 | -20683.58 | 12821.03 | | | |
| Y-7 | -20678.82 | 12831.75 | | | | R-7 | -20674.61 | 12828.05 | | | |
| Y-8 | -20671.24 | 12825.08 | | | | R-8 | -20671.24 | 12825.08 | | | |
| Y-9 | -20667.26 | 12821.57 | | | | R-9 | -20671.20 | 12825.04 | | | |
| Y-10 | -20659.76 | 12814.96 | | | | R-10 | -20679.37 | 12816.40 | | | |
| Y-11 | -20668.92 | 12804.92 | | | | R-11 | -20693.21 | 12805.37 | | | |
| Y-12 | -20678.69 | 12798.47 | | | | R−12 | -20689.97 | 12794.19 | | | |
| Y-13 | -20672.81 | 12789.02 | | | | R-13 | -20700.49 | 12783.83 | | | |
| Y-14 | -20689.09 | 12771.79 | | | | R-14 | -20712.30 | 12772.47 | | | |
| Y-15 | -20700.48 | 12760.95 | | | | R−15 | -20725.45 | 12755.46 | | | |
| Y-16 | -20706.93 | 12756.20 | | | | R-16 | -20728.34 | 12755.34 | | | |
| Y-17 | -20716.92 | 12755.80 | | | | | | | | | |
| Y-18 | -20728.34 | 12755.34 | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |