

# 急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地の座標点位置図

調査年度

平成28年度

急傾斜地の位置

箇所番号


I-0152

箇所名

瀬又2

所在地

千葉県市原市瀬又



# 急傾斜地の崩壊区域調査

様式5-5 危害のおそれのある土地等の座標一覧

調査年度 平成28年度

|         |      |        |     |     |     |          |
|---------|------|--------|-----|-----|-----|----------|
| 急傾斜地の位置 | 箇所番号 | I-0152 | 箇所名 | 瀬又2 | 所在地 | 千葉県市原市瀬又 |
|---------|------|--------|-----|-----|-----|----------|

## 危害のおそれのある土地の座標(土砂災害警戒区域)

| 地点記号 | X(m)     | Y(m)      | 地点記号 | X(m)     | Y(m)      |
|------|----------|-----------|------|----------|-----------|
| Y-1  | 33767.51 | -51058.11 | Y-33 | 33857.06 | -50888.88 |
| Y-2  | 33764.93 | -51043.25 | Y-34 | 33862.81 | -50907.27 |
| Y-3  | 33764.21 | -51039.07 | Y-35 | 33873.70 | -50917.57 |
| Y-4  | 33762.05 | -51026.63 | Y-36 | 33872.64 | -50934.11 |
| Y-5  | 33761.34 | -51022.19 | Y-37 | 33869.48 | -50957.85 |
| Y-6  | 33760.25 | -51015.08 | Y-38 | 33866.02 | -50966.45 |
| Y-7  | 33766.94 | -51014.07 | Y-39 | 33866.31 | -50979.75 |
| Y-8  | 33783.92 | -51002.93 | Y-40 | 33861.21 | -50993.59 |
| Y-9  | 33790.26 | -51001.37 | Y-41 | 33854.59 | -51005.32 |
| Y-10 | 33793.83 | -51002.77 | Y-42 | 33845.64 | -51019.90 |
| Y-11 | 33796.08 | -50993.74 | Y-43 | 33827.43 | -51043.20 |
| Y-12 | 33797.05 | -50984.26 | Y-44 | 33805.51 | -51056.71 |
| Y-13 | 33802.38 | -50970.63 | Y-45 | 33789.21 | -51058.46 |
| Y-14 | 33806.33 | -50959.71 | Y-46 | 33773.80 | -51051.06 |
| Y-15 | 33812.28 | -50950.68 |      |          |           |
| Y-16 | 33812.75 | -50946.34 |      |          |           |
| Y-17 | 33812.39 | -50936.97 |      |          |           |
| Y-18 | 33810.85 | -50919.86 |      |          |           |
| Y-19 | 33819.57 | -50908.07 |      |          |           |
| Y-20 | 33825.02 | -50889.33 |      |          |           |
| Y-21 | 33824.80 | -50871.02 |      |          |           |
| Y-22 | 33824.73 | -50868.89 |      |          |           |
| Y-23 | 33825.57 | -50862.21 |      |          |           |
| Y-24 | 33831.40 | -50861.17 |      |          |           |
| Y-25 | 33832.92 | -50860.90 |      |          |           |
| Y-26 | 33835.28 | -50860.68 |      |          |           |
| Y-27 | 33837.88 | -50860.66 |      |          |           |
| Y-28 | 33840.55 | -50860.74 |      |          |           |
| Y-29 | 33843.91 | -50860.85 |      |          |           |
| Y-30 | 33850.54 | -50861.06 |      |          |           |
| Y-31 | 33853.34 | -50869.52 |      |          |           |
| Y-32 | 33856.96 | -50871.78 |      |          |           |

## 著しい危害のおそれのある土地の座標(土砂災害特別警戒区域)

| 地点記号 | X(m)     | Y(m)      | 地点記号 | X(m)     | Y(m)      |
|------|----------|-----------|------|----------|-----------|
| R-1  | 33765.46 | -51046.29 | R-33 | 33833.21 | -50997.82 |
| R-2  | 33764.93 | -51043.25 | R-34 | 33826.91 | -51013.12 |
| R-3  | 33764.21 | -51039.07 | R-35 | 33816.35 | -51031.02 |
| R-4  | 33763.03 | -51032.27 | R-36 | 33802.91 | -51036.25 |
| R-5  | 33769.24 | -51028.12 | R-37 | 33787.35 | -51037.89 |
| R-6  | 33785.47 | -51018.30 | R-38 | 33771.26 | -51038.30 |
| R-7  | 33798.56 | -51015.31 |      |          |           |
| R-8  | 33803.85 | -51016.76 |      |          |           |
| R-9  | 33808.13 | -51004.56 |      |          |           |
| R-10 | 33811.74 | -50990.61 |      |          |           |
| R-11 | 33817.49 | -50976.11 |      |          |           |
| R-12 | 33821.23 | -50964.32 |      |          |           |
| R-13 | 33827.91 | -50952.34 |      |          |           |
| R-14 | 33829.14 | -50946.64 |      |          |           |
| R-15 | 33829.64 | -50935.38 |      |          |           |
| R-16 | 33828.15 | -50918.47 |      |          |           |
| R-17 | 33836.25 | -50907.73 |      |          |           |
| R-18 | 33840.88 | -50889.11 |      |          |           |
| R-19 | 33840.88 | -50871.40 |      |          |           |
| R-20 | 33838.62 | -50869.20 |      |          |           |
| R-21 | 33839.94 | -50869.23 |      |          |           |
| R-22 | 33843.42 | -50869.30 |      |          |           |
| R-23 | 33844.51 | -50869.33 |      |          |           |
| R-24 | 33849.16 | -50871.60 |      |          |           |
| R-25 | 33849.14 | -50888.99 |      |          |           |
| R-26 | 33850.44 | -50907.48 |      |          |           |
| R-27 | 33852.22 | -50918.02 |      |          |           |
| R-28 | 33852.43 | -50934.47 |      |          |           |
| R-29 | 33850.07 | -50951.37 |      |          |           |
| R-30 | 33846.97 | -50959.07 |      |          |           |
| R-31 | 33843.02 | -50971.92 |      |          |           |
| R-32 | 33839.35 | -50984.80 |      |          |           |