

急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度

2024

急傾斜地の位置

箇所番号


II-132K2300-1

箇所名

天津40

所在地

鴨川市天津



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地等の座標一覧

調査年度 2024

急傾斜地の位置		箇所番号		II-132K2300-1		箇所名		天津40		所在地		鴨川市天津		
危害のおそれのある土地の座標						著しい危害のおそれのある土地の座標								
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-96091.72	30935.86	Y31	-96055.77	30976.12	R1	-96006.34	31041.65	R31	-95987.34	31044.45			
Y2	-96090.37	30936.66	Y32	-96069.13	30973.82	R2	-96016.16	31029.50	R32	-95979.31	31052.76			
Y3	-96063.69	30939.90	Y33	-96080.48	30975.35	R3	-96022.01	31016.30	R33	-95980.39	31058.07			
Y4	-96054.73	30942.69	Y34	-96093.13	30981.93	R4	-96025.60	31005.49	R34	-95981.51	31061.69			
Y5	-96044.07	30943.16	Y35	-96105.13	30987.38	R5	-96021.04	30997.24	R35	-95981.69	31062.29			
Y6	-96008.55	30936.06	Y36	-96105.50	30986.39	R6	-96019.43	30979.32	R36	-95986.64	31061.08			
Y7	-96003.05	30982.91	Y37	-96108.63	30978.02	R7	-96017.56	30956.43	R37	-95995.28	31051.72			
Y8	-96004.21	30998.04	Y38	-96110.67	30972.56	R8	-96040.01	30959.58						
Y9	-95989.45	31001.17	Y39	-96111.46	30971.14	R9	-96056.42	30960.98	R38	-96108.62	31009.09			
Y10	-95990.75	31006.33	Y40	-96113.75	30968.62	R10	-96067.23	30959.20	R39	-96118.42	31005.03			
Y11	-95989.27	31012.02	Y41	-96115.26	30966.96	R11	-96081.55	30962.09	R40	-96115.04	30999.58			
Y12	-95983.79	31021.66	Y42	-96121.30	30960.30	R12	-96099.02	30967.52	R41	-96113.26	30996.70			
Y13	-95978.77	31036.61	Y43	-96116.06	30951.78	R13	-96110.09	30974.11	R42	-96103.44	31004.60			
Y14	-95972.10	31045.13	Y44	-96114.96	30949.33	R14	-96110.67	30972.56	R43	-96104.48	31005.50			
Y15	-95978.74	31052.74	Y45	-96113.28	30945.61	R15	-96111.46	30971.14						
Y16	-95981.51	31061.69	Y46	-96113.05	30943.13	R16	-96113.75	30968.62	R44	-96089.64	31035.90			
Y17	-95981.69	31062.29				R17	-96115.26	30966.96	R45	-96092.79	31036.45			
Y18	-95983.22	31067.23	Y47	-96120.02	31007.59	R18	-96118.80	30963.06	R46	-96091.10	31016.93			
Y19	-95983.66	31068.67	Y48	-96115.04	30999.58	R19	-96096.32	30951.54	R47	-96089.98	31016.82			
Y20	-95986.17	31076.79	Y49	-96110.61	30992.43	R20	-96084.83	30952.62	R48	-96088.60	31035.72			
Y21	-95992.62	31075.65	Y50	-96105.43	30984.08	R21	-96065.55	30950.07						
Y22	-96006.26	31061.76	Y51	-96105.33	30983.93	R22	-96055.56	30951.99						
Y23	-96015.89	31050.12	Y52	-96091.25	30992.90	R23	-96041.59	30953.20						
Y24	-96027.03	31036.23	Y53	-96091.56	30993.20	R24	-96012.62	30946.19						
Y25	-96033.73	31020.50	Y54	-96095.92	30997.50	R25	-96014.37	30980.43						
Y26	-96036.77	31012.41	Y55	-96098.38	30999.92	R26	-96014.36	30997.56						
Y27	-96034.76	30998.23	Y56	-96098.41	30999.96	R27	-96012.82	31003.74						
Y28	-96032.06	30976.55	Y57	-96100.74	31002.22	R28	-96013.44	31013.51						
Y29	-96029.63	30966.41	Y58	-96101.96	31003.32	R29	-96007.72	31024.06						

急傾斜地の崩壊区域調査

様式5-4 危害のおそれのある土地等の座標位置図

調査年度

2024

急傾斜地の位置

箇所番号


II-132K2300-2

箇所名

天津40

所在地

鴨川市天津



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地等の座標一覧

調査年度

2024

[illegible]

平面直角座標系：第Ⅸ系（測地成果2011）