急傾斜地の崩壊区域調書

-4 危害のおそれのな 急傾斜地の位置	箇所番号	<i>I −031K2093</i>	箇所名	松戸新田3	所在地	松戸市松戸新田	調査年度	2023
心灰水心之口	凹川田勺	1 001112000	四///-口	141 /1/1 p4 0	171 11.25	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
								N
								^
			Y2	20				
			YZ					
				Y21\V1				
			Y19\	Y1 /Y2				
			R5 R7	Ø by				
		Y18-		Y3				
		Y17~		R8				
			R4	R9 R10				
		Y16		* ***********************************	Y4			
		/	F	R11	1			
		Y15		R2 R1	1			
		123		112	1			
					/ ^{Y5}			
			V14		√Y6 ✓Y7 ve			
			Y14 Y13		18			
			Y13		19	_ Y10		
						110		
					Y11			
1.500								
1:500 10	20 m							

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度

2023

急傾斜地の位置 箇所番号 I-031K2093 箇所名 松戸新田3	所在地	松戸市松戸新田
---	-----	---------

危害のおそれのある区域の座標(土砂災害警戒区域)					著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)						
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-24641.42	7315.28				R1	-24652.77	7312.35			
Y2	-24642.90	7318.45				R2	-24653.31	7312.02			
Y3	-24642.44	7318.73				R3	-24651.98	7307.96			
Y4	-24651.91	7325.71				R4	-24645.41	7298.30			
Y5	-24663.60	7326.90				R5	-24644.96	7298.59			
Y6	-24665.53	7327.10				R6	-24643.25	7299.68			
Y7	-24665.79	7327.73				R7	-24642.80	7299.96			
Y8	-24666.88	7330.31				R8	-24647.58	7311.01			
Y9	-24667.47	7331.71				R9	-24649.26	7314.52			
Y10	-24670.76	7339.52				R10	-24651.21	7313.31			
Y11	-24681.57	7324.93				R11	-24652.77	7312.35			
Y12	-24665.17	7304.72									
Y13	-24665.19	7304.68									
Y14	-24663.69	7299.83									
Y15	-24656.10	7291.51									
Y16	-24648.79	7296.16									
Y17	-24647.66	7296.87									
Y18	-24644.96	7298.59									
Y19	-24643.25	7299.68									
Y20	-24634.83	7305.03									
Y21	-24641.42	7315.28									

平面直角座標系:第IX系(測地成果2011)