


急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図



急傾斜地の崩壊区域調査

様式5-5 危害のおそれのある土地の座標一覧

調査年度	2023
------	------

急傾斜地の位置	箇所番号	I-031K2095	箇所名	松戸新田5	所在地	松戸市松戸新田
---------	------	------------	-----	-------	-----	---------

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-24531.47	7505.56	Y30	-24564.04	7527.04						
Y2	-24540.41	7501.74	Y31	-24566.08	7531.39						
Y3	-24539.22	7494.87	Y32	-24568.31	7536.16						
Y4	-24538.70	7491.88	Y33	-24570.31	7540.45						
Y5	-24538.35	7489.91									
Y6	-24538.11	7488.51									
Y7	-24536.64	7480.06									
Y8	-24522.07	7485.67									
Y9	-24514.62	7489.96									
Y10	-24501.12	7504.14									
Y11	-24502.94	7507.78									
Y12	-24511.67	7510.60									
Y13	-24512.13	7511.56									
Y14	-24512.17	7511.64									
Y15	-24514.09	7515.59									
Y16	-24516.53	7520.64									
Y17	-24523.20	7514.33									
Y18	-24523.66	7508.70									
Y19	-24524.72	7509.51									
Y20	-24531.47	7505.56									
Y21	-24570.31	7540.45									
Y22	-24584.55	7533.84									
Y23	-24582.19	7529.14									
Y24	-24580.06	7524.90									
Y25	-24577.94	7520.71									
Y26	-24576.57	7517.98									
Y27	-24572.36	7509.63									
Y28	-24558.62	7515.44									
Y29	-24562.94	7524.68									

平面直角座標系: 第Ⅸ系(測地成果2011)