

## 急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地の座標点位置図

調査年度

令和5年度

急傾斜地の位置

箇所番号


I-151K2730

筒所名

有秋台東1

所在地

市原市有秋台東1丁目、有秋台東2丁目



0                      50                      100 m

千葉県

# 急傾斜地の崩壊区域調書

様式5-5(1/2) 危害のおそれのある土地等の座標一覧

様式5－5(1/2) 危害のおそれのある土地等の座標一覧

|         |  |      |            |  |     |       |  |     |                    |  |
|---------|--|------|------------|--|-----|-------|--|-----|--------------------|--|
| 急傾斜地の位置 |  | 箇所番号 | I-151K2730 |  | 箇所名 | 有秋台東1 |  | 所在地 | 市原市有秋台東1丁目、有秋台東2丁目 |  |
|---------|--|------|------------|--|-----|-------|--|-----|--------------------|--|

危害のおそれのある土地の座標(土砂災害警戒区域)

|      |             |            |      |             |            |
|------|-------------|------------|------|-------------|------------|
| 地点記号 | X(m)        | Y(m)       | 地点記号 | X(m)        | Y(m)       |
| Y-1  | -60511.7638 | 19924.9193 | Y-33 | -60558.4128 | 19969.547  |
| Y-2  | -60500.558  | 19942.5056 | Y-34 | -60546.5788 | 19956.187  |
| Y-3  | -60504.2038 | 19944.1482 | Y-35 | -60539.499  | 19949.9044 |
| Y-4  | -60498.8341 | 19949.3578 | Y-36 | -60539.2792 | 19949.6748 |
| Y-5  | -60501.4731 | 19966.9152 | Y-37 | -60542.8415 | 19937.6979 |
| Y-6  | -60517.5856 | 19982.7231 | Y-38 | -60548.0763 | 19924.8218 |
| Y-7  | -60529.7221 | 19995.5118 | Y-39 | -60555.1821 | 19906.6917 |
| Y-8  | -60544.5699 | 20011.204  | Y-40 | -60549.1662 | 19904.6541 |
| Y-9  | -60560.0414 | 20027.2917 | Y-41 | -60545.7106 | 19903.4837 |
| Y-10 | -60578.2552 | 20033.1527 | Y-42 | -60540.3118 | 19901.655  |
| Y-11 | -60592.1686 | 20034.7098 | Y-43 | -60536.863  | 19900.4869 |
| Y-12 | -60604.4266 | 20033.1962 | Y-44 | -60530.8403 | 19898.447  |
| Y-13 | -60621.8613 | 20032.6225 | Y-45 | -60519.2981 | 19915.0275 |
| Y-14 | -60623.5445 | 20038.0355 | Y-46 | -60511.7638 | 19924.9193 |
| Y-15 | -60625.6781 | 20042.2836 | Y-47 | -60438.5259 | 19979.3301 |
| Y-16 | -60642.156  | 20041.0769 | Y-48 | -60458.1812 | 19988.3589 |
| Y-17 | -60661.688  | 20039.921  | Y-49 | -60479.16   | 19986.183  |
| Y-18 | -60681.545  | 20038.5808 | Y-50 | -60494.1475 | 19975.3899 |
| Y-19 | -60681.9224 | 20035.0495 | Y-51 | -60508.7816 | 19963.6596 |
| Y-20 | -60682.6076 | 20028.6374 | Y-52 | -60517.5875 | 19951.2867 |
| Y-21 | -60683.1385 | 20023.6696 | Y-53 | -60511.5881 | 19947.7903 |
| Y-22 | -60684.1449 | 20014.2532 | Y-54 | -60508.9476 | 19946.2515 |
| Y-23 | -60684.2012 | 20013.7262 | Y-55 | -60502.897  | 19942.7253 |
| Y-24 | -60665.2308 | 20009.5275 | Y-56 | -60499.6025 | 19940.8053 |
| Y-25 | -60646.534  | 20006.0531 | Y-57 | -60494.2571 | 19937.6902 |
| Y-26 | -60629.8728 | 20003.0066 | Y-58 | -60490.2089 | 19940.6157 |
| Y-27 | -60626.8964 | 20004.7028 | Y-59 | -60484.5453 | 19943.5033 |
| Y-28 | -60623.7348 | 20006.3932 | Y-60 | -60481.8579 | 19944.2424 |
| Y-29 | -60606.9813 | 20003.604  | Y-61 | -60470.9203 | 19936.2374 |
| Y-30 | -60594.7733 | 20001.3072 | Y-62 | -60459.0103 | 19924.1956 |
| Y-31 | -60587.2077 | 20000.5741 | Y-63 | -60447.3727 | 19912.3968 |
| Y-32 | -60573.2301 | 19985.9559 | Y-64 | -60447.203  | 19912.5572 |

著しい危害のおそれのある土地の座標(土砂災害特別警戒区域)

|      |             |            |      |             |            |
|------|-------------|------------|------|-------------|------------|
| 地点記号 | X(m)        | Y(m)       | 地点記号 | X(m)        | Y(m)       |
| R-1  | -60663.2626 | 20026.4125 | R-33 | -60528.6609 | 19918.214  |
| R-2  | -60663.4771 | 20024.572  | R-34 | -60526.4669 | 19917.4673 |
| R-3  | -60644.6886 | 20020.8167 | R-35 | -60520.4844 | 19928.5051 |
| R-4  | -60628.3063 | 20017.6738 | R-36 | -60509.8625 | 19948.4738 |
| R-5  | -60625.4267 | 20019.3177 | R-37 | -60511.7804 | 19961.1759 |
| R-6  | -60625.1453 | 20022.1158 | R-38 | -60421.2483 | 19937.0897 |
| R-7  | -60624.7115 | 20026.4301 | R-39 | -60433.0202 | 19949.0391 |
| R-8  | -60624.5457 | 20028.0786 | R-40 | -60448.193  | 19964.6361 |
| R-9  | -60627.0615 | 20029.3305 | R-41 | -60466.3156 | 19974.3602 |
| R-10 | -60643.4728 | 20030.5425 | R-42 | -60479.8493 | 19975.1542 |
| R-11 | -60662.6127 | 20031.9877 | R-43 | -60491.8698 | 19967.8263 |
| R-12 | -60663.2626 | 20026.4125 | R-44 | -60504.8574 | 19958.7906 |
| R-13 | -60511.7804 | 19961.1759 | R-45 | -60503.4125 | 19956.9979 |
| R-14 | -60525.3719 | 19975.5967 | R-46 | -60501.5023 | 19954.6279 |
| R-15 | -60537.4357 | 19988.5311 | R-47 | -60500.8103 | 19953.7693 |
| R-16 | -60552.2656 | 20004.4245 | R-48 | -60489.3448 | 19959.4413 |
| R-17 | -60567.3473 | 20020.538  | R-49 | -60480.671  | 19962.0067 |
| R-18 | -60580.326  | 20023.361  | R-50 | -60474.9247 | 19959.0713 |
| R-19 | -60592.9463 | 20024.7367 | R-51 | -60459.3351 | 19948.438  |
| R-20 | -60593.1015 | 20022.7463 | R-52 | -60446.5379 | 19936.1178 |
| R-21 | -60593.4125 | 20018.7583 | R-53 | -60434.836  | 19924.2466 |
| R-22 | -60593.6313 | 20015.9516 | R-54 | -60428.4174 | 19917.0261 |
| R-23 | -60582.1474 | 20014.7485 | R-55 | -60433.0166 | 19904.8307 |
| R-24 | -60575.7383 | 20012.7811 | R-56 | -60436.7179 | 19894.7522 |
| R-25 | -60560.9286 | 19996.7928 | R-57 | -60437.7659 | 19888.231  |
| R-26 | -60546.1831 | 19980.6147 | R-58 | -60449.9517 | 19868.8903 |
| R-27 | -60534.2967 | 19967.4283 | R-59 | -60462.2424 | 19850.629  |
| R-28 | -60523.6982 | 19954.7659 | R-60 | -60457.3693 | 19847.6802 |
| R-29 | -60522.9785 | 19951.1442 | R-61 | -60451.3627 | 19844.0455 |
| R-30 | -60528.8482 | 19931.9441 | R-62 | -60440.2541 | 19863.2978 |
| R-31 | -60533.4454 | 19919.8424 | R-63 | -60428.7298 | 19882.9901 |
| R-32 | -60531.7942 | 19919.2804 | R-64 | -60418.1012 | 19887.9261 |

## 急傾斜地の崩壊区域調書

様式5-5(2/2) 危害のおそれのある土地等の座標一覧

| 様式5-5(2/2) 危害のおそれのある土地等の座標一覧 |      |            |     |       |     | 調査年度               | 令和5年度 |
|------------------------------|------|------------|-----|-------|-----|--------------------|-------|
| 急傾斜地の位置                      | 箇所番号 | I-151K2730 | 箇所名 | 有秋台東1 | 所在地 | 市原市有秋台東1丁目、有秋台東2丁目 |       |

危害のおそれのある土地の座標(土砂災害警戒区域)

| 地点記号 | X(m)        | Y(m)       | 地点記号  | X(m)        | Y(m)       |
|------|-------------|------------|-------|-------------|------------|
| Y-65 | -60449.0398 | 19910.0186 | Y-97  | -60589.7874 | 20079.6938 |
| Y-66 | -60452.5061 | 19900.5413 | Y-98  | -60600.4499 | 20090.7325 |
| Y-67 | -60452.8776 | 19896.9957 | Y-99  | -60619.1727 | 20091.1972 |
| Y-68 | -60465.4366 | 19877.8202 | Y-100 | -60619.7809 | 20083.9805 |
| Y-69 | -60477.0458 | 19859.587  | Y-101 | -60620.0124 | 20081.2325 |
| Y-70 | -60474.6918 | 19858.1625 | Y-102 | -60620.5668 | 20074.6535 |
| Y-71 | -60468.4903 | 19854.4098 | Y-103 | -60620.9715 | 20069.8517 |
| Y-72 | -60457.3693 | 19847.6802 |       |             |            |
| Y-73 | -60448.8949 | 19842.5521 |       |             |            |
| Y-74 | -60442.1405 | 19838.4649 |       |             |            |
| Y-75 | -60431.9978 | 19858.5365 |       |             |            |
| Y-76 | -60420.9569 | 19878.4819 |       |             |            |
| Y-77 | -60401.4279 | 19881.8126 |       |             |            |
| Y-78 | -60397.8588 | 19893.4477 |       |             |            |
| Y-79 | -60391.5576 | 19925.5322 |       |             |            |
| Y-80 | -60409.513  | 19948.182  |       |             |            |
| Y-81 | -60421.3467 | 19960.1976 |       |             |            |
| Y-82 | -60438.5259 | 19979.3301 |       |             |            |
| Y-83 | -60620.9715 | 20069.8517 |       |             |            |
| Y-84 | -60621.4066 | 20064.6888 |       |             |            |
| Y-85 | -60616.1341 | 20066.842  |       |             |            |
| Y-86 | -60615.9131 | 20066.5909 |       |             |            |
| Y-87 | -60613.0391 | 20052.3645 |       |             |            |
| Y-88 | -60602.7391 | 20031.1019 |       |             |            |
| Y-89 | -60601.48   | 20029.317  |       |             |            |
| Y-90 | -60593.9839 | 20031.7516 |       |             |            |
| Y-91 | -60591.969  | 20032.406  |       |             |            |
| Y-92 | -60586.7376 | 20034.1051 |       |             |            |
| Y-93 | -60584.697  | 20034.7679 |       |             |            |
| Y-94 | -60577.2266 | 20037.1942 |       |             |            |
| Y-95 | -60577.9552 | 20041.5626 |       |             |            |
| Y-96 | -60584.1639 | 20060.8573 |       |             |            |

## 著しい危害のおそれのある土地の座標(土砂災害特別警戒区域)

[illegible]