急傾斜地の崩壊区域調書

<u>-4 危害のおそれのあ</u>	る土地等の座標位	直凶		,			調査年度	令和5年	'吳
急傾斜地の位置	箇所番号	<i>II −031K2031</i>	箇所名	幸田4	所在地	松戸市幸田37	- 目		
									Ν
									I N
									1
			Y6~	/14 / R5~R7					
			VIE	\ /					
			Y15	Y5 Y4 R2					
			Y16 🥎	R4R3	Y3				
			V47	R8 📞 /					
			Y17 0	R9 R10 R1					
			Y18						
			Y19~	Y25 Y1					
				Y1					
								4.4.000	
								1:1,000	
								0.5	-
							0	25	5

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度

令和5年度

急傾斜地の位置 | 箇所番号 | II-031K2031 | 箇所名 | 幸田4 | 所在地 | 松戸市幸田3丁目

危害のおそれのある区域の座標(土砂災害警戒区域)				著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)							
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-16876.29	8559.88				R1	-16867.49	8558.88			
Y2	-16871.80	8570.80				R2	-16858.43	8562.74			
Y3	-16859.54	8578.73				R3	-16858.25	8560.18			
Y4	-16858.25	8560.18				R4	-16858.01	8556.78			
Y5	-16858.01	8556.78				R5	-16857.87	8554.80			
Y6	-16857.87	8554.80				R6	-16857.72	8553.29			
Y7	-16857.72	8553.29				R7	-16857.59	8552.55			
Y8	-16857.48	8551.83				R8	-16864.44	8550.45			
Y9	-16857.08	8549.64				R9	-16865.54	8553.49			
Y10	-16856.96	8549.06				R10	-16867.21	8558.11			
Y11	-16856.84	8548.45									
Y12	-16856.63	8547.30									
Y13	-16856.33	8545.88									
Y14	-16855.97	8544.64									
Y15	-16854.45	8539.39									
Y16	-16859.72	8537.41									
Y17	-16866.28	8539.49									
Y18	-16868.29	8542.15									
Y19	-16870.13	8544.59									
Y20	-16870.82	8545.71									
Y21	-16871.60	8547.21									
Y22	-16871.82	8547.77									
Y23	-16872.33	8549.06									
Y24	-16872.85	8550.49									
Y25	-16874.34	8554.55									
				· ·							

平面直角座標系:第区系(測地成果2011)