
## 急傾斜地の崩壊区域調書



## 急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧 調査年度 *平成29年度* 急傾斜地の位置 歯所番号 II-1059 歯所 名 原4 所在地 柏市泉

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y−1	-17643.17	18903.62				R-1	-17648.36	18906.29			
Y-2	-17637.12	18898.31				R-2	-17644.96	18897.52			
Y-3	-17628.14	18888.08				R-3	-17638.32	18885.87			
Y-4	-17623.95	18863.13				R−4	-17635.11	18866.75			
Y−5	-17646.20	18837.47				R−5	-17653.07	18848.51			
Y-6	-17646.20	18837.47				R−6	-17653.07	18848.51			
Y-7	-17671.92	18825.63				R−7	-17673.15	18838.18			
Y-8	-17672.22	18828.68				R-8	-17673.88	18845.73			
Y-9	-17673.88	18845.73				R-9	-17674.48	18851.89			
Y-10	-17675.07	18857.93				R−10	-17659.73	18859.22			
Y-11	-17675.66	18863.93				R-11	-17659.73	18859.22			
Y-12	-17676.04	18867.88				R−12	-17646.59	18870.47			
Y-13	-17667.74	18872.09				R−13	-17648.87	18883.58			
Y-14	-17667.74	18872.09				R-14	-17653.31	18896.68			
Y−15	-17661.33	18875.26				R−15	-17652.22	18908.28			
Y-16	-17664.10	18880.28				R−16	-17652.17	18908.26			
Y-17	-17669.31	18895.07									
Y-18	-17665.39	18915.06									
Y-19	-17659.90	18912.24									
Y-20	-17656.50	18910.48									
Y-21	-17652.17	18908.26									