

急傾斜地の崩壊区域調査

様式5-4 危害のおそれのある土地等の座標位置図

調査年度

2023

急傾斜地の位置

箇所番号


II-122K2069

箇所名

下原5

所在地

いすみ市下原



1:1,000

0 25 50 m

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度	2023
------	------

急傾斜地の位置	箇所番号	II-122K2069	箇所名	下原5	所在地	いすみ市下原
---------	------	-------------	-----	-----	-----	--------

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-80187.30	46267.60				R1	-80187.30	46267.60			
Y2	-80183.02	46263.05				R2	-80183.02	46263.05			
Y3	-80179.14	46260.38				R3	-80179.14	46260.38			
Y4	-80176.59	46259.43				R4	-80176.59	46259.43			
Y5	-80172.16	46258.82				R5	-80172.16	46258.82			
Y6	-80169.08	46258.62				R6	-80169.08	46258.62			
Y7	-80164.30	46258.46				R7	-80164.30	46258.46			
Y8	-80160.14	46258.61				R8	-80160.14	46258.61			
Y9	-80155.55	46259.58				R9	-80155.55	46259.58			
Y10	-80150.69	46261.14				R10	-80150.69	46261.14			
Y11	-80147.17	46262.68				R11	-80147.17	46262.68			
Y12	-80144.82	46263.75				R12	-80144.82	46263.75			
Y13	-80141.38	46266.54				R13	-80141.38	46266.54			
Y14	-80138.54	46269.01				R14	-80138.54	46269.01			
Y15	-80131.87	46274.88				R15	-80131.87	46274.88			
Y16	-80127.37	46278.59				R16	-80127.37	46278.59			
Y17	-80124.05	46281.43				R17	-80124.05	46281.43			
Y18	-80120.98	46284.08				R18	-80120.98	46284.08			
Y19	-80120.92	46284.01				R19	-80120.92	46284.01			
Y20	-80112.99	46275.00				R20	-80116.76	46279.29			
Y21	-80108.49	46269.89				R21	-80129.31	46268.44			
Y22	-80106.38	46267.49				R22	-80141.77	46257.44			
Y23	-80118.79	46256.45				R23	-80156.33	46251.96			
Y24	-80132.93	46243.60				R24	-80174.64	46250.44			
Y25	-80154.46	46235.39				R25	-80193.20	46260.28			
Y26	-80177.36	46232.79									
Y27	-80204.85	46245.81									
Y28	-80204.03	46246.84									
Y29	-80198.58	46253.60									

平面直角座標系：第Ⅸ区系(測地成果2011)