5-4 危害のおそれのあ	る土地等の座標位	☑置図	<b>本記</b> 名	±CΠΩςς	にた地		調査年度	2023	}
急傾斜地の位置	の工地等の医療型	II −122K2253−1   Y20~Y30	R10 Y31 R11 R12	新田65  Y17  Y18  R6  R7  R4  R3  R3  Y33  Y33  Y2  Y17  Y2  Y1	所在地 Y16 Y15 Y14 Y13 Y12 Y11 Y18 Y7 Y6	いすみ市新田、若	<u> </u>	2023	N A
							0	1:1,000 <sub>25</sub>	5(

様式5-5 危害のおそれのある土地の座標一覧

調査年度 2023

急傾斜地の位置 箇所番号 II-122K2253-1 箇所名 新田65 新田65 所在地 いすみ市新田、若山

:	危害のおそれ	のある区域の	の座標(土砂ジ	<b>泛害警戒区</b> 域	;)	著しい	危害のおそれ	このある区域	の座標(土砂ジ	災害特別警戒	戍区域)
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記 <del>号</del>	X(m)	Y(m)
Y1	-81245.28	49222.81	Y31	-81206.70	49190.12	R1	-81235.24	49214.30			
Y2	-81245.21	49222.82	Y32	-81227.15	49207.45	R2	-81229.10	49220.31			
Y3	-81237.19	49227.89	Y33	-81237.15	49215.92	R3	-81217.40	49222.95			
Y4	-81227.46	49232.60				R4	-81200.22	49221.87			
Y5	-81215.27	49238.47				R5	-81183.46	49218.99			
Y6	-81204.58	49243.41				R6	-81183.57	49218.64			
Y7	-81200.78	49244.98				R7	-81186.51	49209.13			
Y8	-81200.53	49246.49				R8	-81188.27	49203.41			
Y9	-81199.06	49258.94				R9	-81192.23	49191.98			
Y10	-81196.80	49258.96				R10	-81201.70	49194.78			
Y11	-81195.03	49256.66				R11	-81206.86	49195.18			
Y12	-81190.80	49252.59				R12	-81209.14	49195.15			
Y13	-81186.83	49249.52				R13	-81211.03	49193.79			
Y14	-81183.12	49247.03				R14	-81227.15	49207.45			
Y15	-81177.62	49244.44									
Y16	-81175.83	49243.72									
Y17	-81183.57	49218.64									
Y18	-81186.51	49209.13									
Y19	-81188.27	49203.41									
Y20	-81193.83	49187.36									
Y21	-81193.86	49187.23									
Y22	-81194.29	49185.64									
Y23	-81194.69	49183.19									
Y24	-81194.79	49181.25									
Y25	-81195.77	49181.81									
Y26	-81197.37	49182.70									
Y27	-81197.71	49183.10									
Y28	-81198.47	49183.53									
Y29	-81199.08	49183.66									
Y30	-81199.59	49184.09									

t5-4 危害のおそれのあ	る土地等の座標位	置図					調査年度	2023	
急傾斜地の位置	箇所番号	II -122K2253-2	箇所名	新田65	所在地	いすみ市新田、若	Щ		
									Ν
									lack
									$\wedge$
									, ,
				Y1					
			Y	′2					
				\ \					
				Y3 •					
				\ \					
				Y13					
				1 7					
				R1					
				R2					
				R6 Y12 Y4 R3					
				Y4 <b>♥</b> R3					
				\ \					
				\ \					
				\ \					
				R5					
				Y5 Y11					
				Y10					
				Y6 Y9 Y9					
				Y7 <sup>18</sup>					
								1:1 000	
							0	1:1,000 <sup>25</sup>	50
								23	50

様式5-5 危害のおそれのある土地の座標一覧

調査年度

2023

急傾斜地の位置	箇所番号	II -122K2253-2	箇所名	新田65	所在地	いすみ市新田、若山

	危害のおそれ	のある区域の	の座標(土砂災	<b>と</b> 害警戒区域	;)	著しい	危害のおそれ	ιのある区域	の座標(土砂ジ	災害特別警戒	<b>戊区</b> 域)
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-81218.11	49215.23				R1	-81253.16	49225.16			
Y2	-81221.57	49210.13				R2	-81255.69	49219.87			
Y3	-81234.91	49213.93				R3	-81265.80	49222.75			
Y4	-81265.80	49222.75				R4	-81287.48	49228.94			
Y5	-81293.49	49230.65				R5	-81285.67	49234.37			
Y6	-81300.20	49232.57				R6	-81263.33	49228.04			
Y7	-81302.58	49233.25									
Y8	-81301.25	49236.66									
Y9	-81300.23	49238.49									
Y10	-81298.51	49238.01									
Y11	-81291.71	49236.08									
Y12	-81263.33	49228.04									
Y13	-81245.18	49222.90									
			1								

式5-4 危害のおそれのあ	る土地等の座標位	置図					調査年度	2023	}
式5-4 危害のおそれのあ 急傾斜地の位置	箇所番号	II −122K2253−3	箇所名	新田65	所在地	いすみ市新田、若口	Ц		
		I ILLINESU U		Y14 Y13 Y16 Y15 Y12 Y18 R1 R9 Y4~Y11 R4~R8					× ×
							0	1:1,000 <sup>25</sup>	50 m

様式5-5 危害のおそれのある土地の座標一覧

調査年度

2023

		• • • • • • •								
急傾	斜地の位置	箇所番号	II −122K2253−3	箇所名		新田65	所在地	いすみ市新田、若	山	
	1	 危害のおそれ		· 《害警戒区域	;)	著しい危害のおそれのある図	 返域の座標(土砂	 災害特別警戒区	域)	

1	危害のおそれ	のある区域の	の座標(土砂災	害警戒区域	)	著しい	危害のおそれ	1のある区域	の座標(土砂ジ	災害特別警戒	坟区域)
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-81187.44	49236.79				R1	-81184.97	49241.46			
Y2	-81215.85	49238.16				R2	-81198.08	49246.34			
Y3	-81198.90	49245.97				R3	-81190.05	49250.04			
Y4	-81190.05	49250.04				R4	-81188.82	49250.61			
Y5	-81188.82	49250.61				R5	-81186.75	49251.72			
Y6	-81186.75	49251.72				R6	-81185.12	49252.92			
Y7	-81185.12	49252.92				R7	-81183.27	49254.99			
Y8	-81183.27	49254.99				R8	-81182.27	49256.24			
Y9	-81181.21	49257.58				R9	-81182.77	49245.63			
Y10	-81179.01	49260.66									
Y11	-81178.23	49261.75									
Y12	-81176.34	49264.39									
Y13	-81173.92	49264.60									
Y14	-81174.50	49261.28									
Y15	-81178.21	49254.26									
Y16	-81179.17	49252.44									
Y17	-81182.77	49245.63									
Y18	-81185.67	49240.13									

5-4 危害のおそれのあ 急傾斜地の位置	の工地寺の座標位	世   1001/0050 4	# = C # 7	立に口へに		しいまれまが田 サー	調査年度	2023	
思傾斜地の位直 ニュー	固別番号	II −122K2253−4	箇所名	新田65	所在地	いすみ市新田、若∟	Ц		
									Ν
									IN A
									1
									,
			<u> </u>	.V12					
			Y7~						
			700	Y6 Y5Y4Y3 R2					
			V F	R7 R6 D5 D4 D0	Y2				
			<u>Q</u>	No RoR4R3					
			C	<u> </u>					
			V14~,V24		/				
			Y14~Y24						
			R8∼R1	12/					
				R1					
				Y1					
								1:1,000	
							0	25	5

様式5-5 危害のおそれのある土地の座標一覧

調査年度

2023

急傾斜地の位置	箇所番号	II −122K2253−4	箇所名	新田65	所在地	いすみ市新田、若山
---------	------	----------------	-----	------	-----	-----------

	厄害のおそれ 	いめる区域(	の座標(土砂災	. 音誉戒区域	)	者しい	厄吾のおそれ 	1のめる区域	の座標(土砂ジ	以吉特別警刑 ————————————————————————————————————	K区域)
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-81208.90	49299.40				R1	-81204.13	49289.25			
Y2	-81187.34	49313.88				R2	-81186.35	49294.80			
Y3	-81186.00	49288.20				R3	-81186.00	49288.20			
Y4	-81185.88	49285.92				R4	-81185.88	49285.92			
Y5	-81185.74	49283.24				R5	-81185.74	49283.24			
Y6	-81185.11	49278.53				R6	-81185.11	49278.53			
Y7	-81183.89	49273.76				R7	-81184.31	49275.40			
Y8	-81182.67	49271.01				R8	-81198.12	49277.62			
Y9	-81182.04	49269.95				R9	-81198.18	49277.69			
Y10	-81180.93	49268.10				R10	-81199.85	49280.13			
Y11	-81179.02	49265.88				R11	-81201.07	49282.74			
Y12	-81177.44	49264.61				R12	-81202.07	49284.86			
Y13	-81175.19	49262.81									
Y14	-81184.73	49267.19									
Y15	-81186.35	49268.25									
Y16	-81190.56	49270.99									
Y17	-81192.78	49272.49									
Y18	-81193.06	49272.72									
Y19	-81195.28	49274.51									
Y20	-81196.95	49276.30									
Y21	-81198.18	49277.69									
Y22	-81199.85	49280.13									
Y23	-81201.07	49282.74									
Y24	-81202.07	49284.86									

5-4 危害のおそれのあ	る土地等の座標位	置図					調査年度	2023	
5-4 危害のおそれのあ 急傾斜地の位置	箇所番号	II −122K2253−5	箇所名	新田65	所在地	いすみ市新田、	若山		
		•							
									Ņ
									lack
				D10					
				Y15Y14Y13 R8 Y12 Y11	- 1440				
			Y1 🔾	7,10,10	— <b>∽</b> Y10				
			\	R1 R11 R9	/				
			\	\ /	Y9				
			Y2 🔷	R2 R7	<b>–</b> 19				
			\	1 / /					
			<b>\</b>	R3 R4 \ R5					
				R5 ×7 Y8					
				R5 Y5 Y6 Y7 Y8					
				Y3 Y5R6 TO					
								1:1,000	
							0	25	5

様式5-5 危害のおそれのある土地の座標一覧

調査年度

2023

急傾斜地の位置	箇所番号	II −122K2253−5	箇所名	新田65	所在地	いすみ市新田、若山
---------	------	----------------	-----	------	-----	-----------

危害のおそれのある区域の座標(土砂災害警戒区域)					)	著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-81186.37	49293.85				R1	-81186.95	49306.48			
Y2	-81196.60	49297.95				R2	-81196.20	49308.45			
Y3	-81211.05	49303.16				R3	-81209.57	49309.74			
Y4	-81209.56	49309.79				R4	-81209.56	49309.79			
Y5	-81208.41	49314.87				R5	-81208.41	49314.87			
Y6	-81206.96	49321.31				R6	-81208.17	49315.94			
Y7	-81205.69	49326.93				R7	-81195.78	49319.63			
Y8	-81204.76	49331.06				R8	-81187.08	49321.30			
Y9	-81195.18	49335.43				R9	-81187.33	49314.57			
Y10	-81186.45	49338.41				R10	-81187.30	49314.03			
Y11	-81186.75	49330.26				R11	-81187.07	49308.99			
Y12	-81186.82	49328.42									
Y13	-81187.33	49314.57									
Y14	-81187.30	49314.03									
Y15 -81187.07	-81187.07	49308.99									