

# 急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度

2024

急傾斜地の位置

箇所番号


II-132K2390

箇所名

浜荻5

所在地

鴨川市浜荻、天津



# 急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

|      |      |
|------|------|
| 調査年度 | 2024 |
|------|------|

|         |      |             |     |     |     |          |
|---------|------|-------------|-----|-----|-----|----------|
| 急傾斜地の位置 | 箇所番号 | II-132K2390 | 箇所名 | 浜荻5 | 所在地 | 鶴川市浜荻、天津 |
|---------|------|-------------|-----|-----|-----|----------|

| 危害のおそれのある区域の座標 |           |          |      |           |          | 著しい危害のおそれのある区域の座標 |           |          |      |           |          |
|----------------|-----------|----------|------|-----------|----------|-------------------|-----------|----------|------|-----------|----------|
| 地点記号           | X(m)      | Y(m)     | 地点記号 | X(m)      | Y(m)     | 地点記号              | X(m)      | Y(m)     | 地点記号 | X(m)      | Y(m)     |
| Y1             | -97228.02 | 28530.11 | Y31  | -97115.15 | 28564.54 | R1                | -97213.40 | 28524.04 | R31  | -97162.36 | 28531.38 |
| Y2             | -97244.91 | 28554.19 | Y32  | -97117.13 | 28563.19 | R2                | -97207.69 | 28541.78 | R32  | -97196.32 | 28517.12 |
| Y3             | -97236.77 | 28566.99 | Y33  | -97120.11 | 28561.36 | R3                | -97200.49 | 28554.36 | R33  | -97205.26 | 28520.66 |
| Y4             | -97233.90 | 28574.90 | Y34  | -97123.21 | 28559.34 | R4                | -97197.29 | 28564.17 | R34  | -97205.86 | 28520.91 |
| Y5             | -97230.26 | 28585.81 | Y35  | -97126.18 | 28557.55 | R5                | -97193.59 | 28575.42 |      |           |          |
| Y6             | -97216.99 | 28582.05 | Y36  | -97129.40 | 28555.89 | R6                | -97182.16 | 28572.17 |      |           |          |
| Y7             | -97182.16 | 28572.17 | Y37  | -97130.80 | 28555.33 | R7                | -97173.73 | 28569.79 |      |           |          |
| Y8             | -97173.73 | 28569.79 | Y38  | -97132.06 | 28553.93 | R8                | -97160.77 | 28566.03 |      |           |          |
| Y9             | -97160.77 | 28566.03 | Y39  | -97133.77 | 28552.91 | R9                | -97140.73 | 28558.54 |      |           |          |
| Y10            | -97140.73 | 28558.54 | Y40  | -97136.00 | 28550.79 | R10               | -97136.07 | 28557.30 |      |           |          |
| Y11            | -97136.07 | 28557.30 | Y41  | -97138.11 | 28548.79 | R11               | -97133.70 | 28556.77 |      |           |          |
| Y12            | -97133.70 | 28556.77 | Y42  | -97140.32 | 28546.69 | R12               | -97130.61 | 28556.69 |      |           |          |
| Y13            | -97130.61 | 28556.69 | Y43  | -97142.89 | 28544.47 | R13               | -97128.56 | 28557.23 |      |           |          |
| Y14            | -97128.56 | 28557.23 | Y44  | -97145.51 | 28542.42 | R14               | -97123.27 | 28560.06 |      |           |          |
| Y15            | -97123.27 | 28560.06 | Y45  | -97148.05 | 28540.06 | R15               | -97113.80 | 28566.11 |      |           |          |
| Y16            | -97112.55 | 28566.92 | Y46  | -97151.12 | 28537.22 | R16               | -97118.10 | 28562.60 |      |           |          |
| Y17            | -97105.97 | 28572.78 | Y47  | -97154.16 | 28534.40 | R17               | -97120.11 | 28561.36 |      |           |          |
| Y18            | -97105.20 | 28573.31 | Y48  | -97156.78 | 28531.97 | R18               | -97123.21 | 28559.34 |      |           |          |
| Y19            | -97102.03 | 28575.52 | Y49  | -97159.42 | 28529.53 | R19               | -97126.18 | 28557.55 |      |           |          |
| Y20            | -97099.37 | 28575.65 | Y50  | -97162.08 | 28526.94 | R20               | -97129.40 | 28555.89 |      |           |          |
| Y21            | -97096.94 | 28575.69 | Y51  | -97164.69 | 28524.16 | R21               | -97130.80 | 28555.33 |      |           |          |
| Y22            | -97095.89 | 28575.71 | Y52  | -97168.08 | 28520.71 | R22               | -97132.06 | 28553.93 |      |           |          |
| Y23            | -97097.64 | 28574.73 | Y53  | -97169.12 | 28519.64 | R23               | -97133.77 | 28552.91 |      |           |          |
| Y24            | -97101.03 | 28574.89 | Y54  | -97180.43 | 28510.56 | R24               | -97136.00 | 28550.79 |      |           |          |
| Y25            | -97104.96 | 28572.68 | Y55  | -97180.82 | 28510.57 | R25               | -97138.11 | 28548.79 |      |           |          |
| Y26            | -97107.24 | 28570.60 | Y56  | -97182.31 | 28510.61 | R26               | -97140.32 | 28546.69 |      |           |          |
| Y27            | -97109.38 | 28568.66 | Y57  | -97189.67 | 28514.03 | R27               | -97140.86 | 28546.22 |      |           |          |
| Y28            | -97111.25 | 28566.96 | Y58  | -97196.12 | 28517.04 | R28               | -97142.66 | 28544.93 |      |           |          |
| Y29            | -97112.99 | 28565.82 | Y59  | -97205.26 | 28520.66 | R29               | -97143.44 | 28544.24 |      |           |          |
| Y30            | -97113.20 | 28565.69 | Y60  | -97205.86 | 28520.91 | R30               | -97144.05 | 28543.97 |      |           |          |

平面直角座標系：第Ⅸ区系(測地成果2011)

## 急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

|      |      |
|------|------|
| 調査年度 | 2024 |
|------|------|

|         |      |             |     |     |     |          |
|---------|------|-------------|-----|-----|-----|----------|
| 急傾斜地の位置 | 箇所番号 | II-132K2390 | 箇所名 | 浜荻5 | 所在地 | 鴨川市浜荻、天津 |
|---------|------|-------------|-----|-----|-----|----------|

[illegible]

平面直角座標系:第Ⅸ系(測地成果2011)