


急傾斜地の崩壊区域調査

様式5-4 危害のおそれのある土地等の座標位置図

調査年度	平成24年度
------	--------

急傾斜地の位置	箇所番号	II-060012	箇所名	須賀4	所在地	印旛郡栄町須賀
---------	------	-----------	-----	-----	-----	---------



急傾斜地の崩壊区域調書

様式5ー5 危害のおそれのある土地等の座標一覧

調査年度 平成24年度

急傾斜地の位置		箇所番号		II-060012		箇所名		須賀4		所在地		印旛郡栄町須賀					
危害の恐れのある土地の座標						著しい危害の恐れのある土地の座標											
地点記号		X(m)		Y(m)		地点記号		X(m)		Y(m)		地点記号		X(m)		Y(m)	
Y-1		-16861.03		38658.39								R-1		-16856.05		38664.88	
Y-2		-16856.70		38664.03								R-2		-16852.26		38669.80	
Y-3		-16852.26		38669.80								R-3		-16850.47		38672.13	
Y-4		-16846.41		38677.42								R-4		-16858.91		38680.35	
Y-5		-16843.31		38681.45								R-5		-16865.68		38692.76	
Y-6		-16840.32		38685.34								R-6		-16871.89		38684.20	
Y-7		-16848.14		38692.96								R-7		-16875.15		38679.71	
Y-8		-16855.92		38706.20								R-8		-16876.95		38677.23	
Y-9		-16860.21		38700.29								R-9		-16866.03		38672.01	
Y-10		-16861.79		38698.11								R-10		-16856.05		38664.88	
Y-11		-16871.89		38684.20								R-11		-16914.61		38707.51	
Y-12		-16875.15		38679.71								R-12		-16912.46		38711.02	
Y-13		-16887.16		38663.15								R-13		-16912.41		38711.09	
Y-14		-16872.29		38664.67								R-14		-16922.34		38720.72	
Y-15		-16861.03		38658.39								R-15		-16924.35		38717.68	
Y-16		-16917.79		38702.32								R-16		-16914.61		38707.51	
Y-17		-16915.82		38705.53													
Y-18		-16912.46		38711.02													
Y-19		-16910.05		38714.95													
Y-20		-16905.99		38721.57													
Y-21		-16904.82		38723.47													
Y-22		-16914.62		38732.39													
Y-23		-16916.57		38729.44													
Y-24		-16920.13		38724.05													
Y-25		-16922.34		38720.72													
Y-26		-16926.19		38714.88													
Y-27		-16927.85		38712.37													
Y-28		-16917.79		38702.32													