


急傾斜地の崩壊区域調査

様式5-4 危害のおそれのある土地等の座標位置図

調査年度	平成24年度
------	--------

急傾斜地の位置	箇所番号	II-060011	箇所名	安食7	所在地	印旛郡栄町安食
---------	------	-----------	-----	-----	-----	---------



急傾斜地の崩壊区域調書

様式5ー5 危害のおそれのある土地等の座標一覧

調査年度 平成24年度

急傾斜地の位置		箇所番号	II-060011	箇所名	安食7	所在地	印旛郡栄町安食	
危害の恐れのある土地の座標						著しい危害の恐れのある土地の座標		
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-17906.24	36726.59	Y-29	-17903.04	36865.05	R-1	-17866.89	36738.24
Y-2	-17870.86	36734.19	Y-30	-17906.58	36866.88	R-2	-17863.59	36741.62
Y-3	-17868.37	36736.73	Y-31	-17911.93	36869.65	R-3	-17863.43	36741.78
Y-4	-17863.59	36741.62	Y-32	-17924.36	36876.07	R-4	-17863.42	36770.32
Y-5	-17859.53	36745.77	Y-33	-17929.98	36878.98	R-5	-17870.93	36786.36
Y-6	-17857.54	36747.80	Y-34	-17940.36	36884.35	R-6	-17882.31	36797.43
Y-7	-17852.54	36752.93	Y-35	-17942.15	36864.58	R-7	-17892.06	36813.11
Y-8	-17851.06	36782.95	Y-36	-17936.14	36862.06	R-8	-17903.86	36825.37
Y-9	-17859.24	36798.20	Y-37	-17930.72	36859.78	R-9	-17930.23	36823.62
Y-10	-17870.14	36809.48	Y-38	-17922.04	36856.14	R-10	-17945.81	36838.63
Y-11	-17879.44	36825.37	Y-39	-17915.75	36853.50	R-11	-17964.56	36847.39
Y-12	-17890.50	36837.15	Y-40	-17912.82	36852.26	R-12	-17965.03	36847.01
Y-13	-17917.56	36833.64				R-13	-17966.75	36845.66
Y-14	-17931.95	36849.63				R-14	-17968.99	36843.90
Y-15	-17950.88	36858.16				R-15	-17954.21	36831.97
Y-16	-17951.75	36857.47				R-16	-17945.64	36811.45
Y-17	-17958.74	36851.97				R-17	-17934.41	36798.42
Y-18	-17965.03	36847.01				R-18	-17921.48	36784.51
Y-19	-17966.75	36845.66				R-19	-17908.86	36771.12
Y-20	-17973.51	36840.33				R-20	-17895.49	36761.48
Y-21	-17961.40	36826.26				R-21	-17885.66	36747.61
Y-22	-17960.32	36799.84				R-22	-17866.89	36738.24
Y-23	-17963.95	36772.36				R-23	-17929.04	36859.07
Y-24	-17950.05	36756.74				R-24	-17918.84	36873.22
Y-25	-17935.58	36744.67				R-25	-17924.36	36876.07
Y-26	-17921.08	36735.56				R-26	-17929.98	36878.98
Y-27	-17906.24	36726.59				R-27	-17930.55	36879.27
Y-28	-17912.82	36852.26				R-28	-17935.83	36861.93