


急傾斜地の崩壊区域調査

様式5-4 危害のおそれのある土地等の座標位置図

調査年度	平成29年度
------	--------

急傾斜地の位置	箇所番号	II-3082	箇所名	一宮25	所在地	一宮町一宮松子
---------	------	---------	-----	------	-----	---------



急傾斜地の崩壊区域調書

様式5ー5 危害のおそれのある土地等の座標一覧

調査年度 平成29年度

急傾斜地の位置		箇所番号		II-3082		箇所名		一宮25		所在地		一宮町一宮松子			
危害の恐れのある土地の座標						著しい危害の恐れのある土地の座標									
地点記号		X(m)	Y(m)	地点記号		X(m)	Y(m)	地点記号		X(m)	Y(m)	地点記号		X(m)	Y(m)
Y-1		47596.59	-71334.16	Y-29		47598.40	-71321.84	R-1		47569.58	-71382.36				
Y-2		47598.93	-71356.87	Y-30		47596.65	-71327.45	R-2		47565.33	-71380.42				
Y-3		47600.22	-71370.50					R-3		47563.68	-71367.04				
Y-4		47586.03	-71376.24					R-4		47563.87	-71357.45				
Y-5		47574.43	-71384.57					R-5		47554.73	-71338.59				
Y-6		47565.33	-71380.42					R-6		47552.22	-71330.94				
Y-7		47558.44	-71376.44					R-7		47549.52	-71308.27				
Y-8		47553.98	-71367.58					R-8		47552.79	-71301.30				
Y-9		47549.55	-71356.75					R-9		47552.55	-71294.48				
Y-10		47539.53	-71322.40					R-10		47552.00	-71266.98				
Y-11		47537.21	-71307.10					R-11		47567.87	-71240.53				
Y-12		47536.42	-71302.18					R-12		47573.62	-71235.14				
Y-13		47536.87	-71298.26					R-13		47584.26	-71243.07				
Y-14		47538.77	-71288.63					R-14		47593.70	-71254.42				
Y-15		47540.39	-71282.75					R-15		47608.27	-71271.56				
Y-16		47540.65	-71279.77					R-16		47594.11	-71284.97				
Y-17		47543.53	-71263.03					R-17		47589.85	-71291.97				
Y-18		47544.08	-71251.60					R-18		47591.18	-71302.13				
Y-19		47560.15	-71226.36					R-19		47594.23	-71309.58				
Y-20		47578.23	-71238.15					R-20		47589.31	-71317.16				
Y-21		47584.26	-71243.07					R-21		47578.82	-71321.52				
Y-22		47593.70	-71254.42					R-22		47579.13	-71325.74				
Y-23		47607.67	-71270.86					R-23		47583.93	-71333.91				
Y-24		47622.92	-71288.79					R-24		47585.68	-71346.77				
Y-25		47621.52	-71304.32					R-25		47585.00	-71363.83				
Y-26		47611.95	-71310.27					R-26		47571.20	-71370.14				
Y-27		47605.73	-71313.40												
Y-28		47601.57	-71317.42												