

急傾斜地の崩壊区域調査

様式5-4 平坦部の展開図

調査年度

平成27年度

急傾斜地の位置

箇所番号


II-4897

箇所名

山本7

所在地

館山市山本



- 凡 例**
- 危害の恐れのある土地等の端点
 - 危害のおそれのある土地の区域
 - 著しい危害のおそれのある土地の区域
 - Y-1 危害の恐れのある土地 地点記号
 - R-1 著しい危害の恐れのある土地 地点記号

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地等の座標一覧

調査年度 平成27年度

急傾斜地の位置	箇所番号	II-4897	箇所名	山本7	所在地	館山市山本
危害のおそれのある土地の座標						
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	
Y-1	5492.61	-112013.66	Y-29	5510.56	-111986.95	
Y-2	5452.40	-112019.98	Y-30	5503.79	-111999.58	
Y-3	5433.29	-111989.75				
Y-4	5432.33	-111981.31				
Y-5	5442.72	-111980.93				
Y-6	5445.73	-111980.82				
Y-7	5447.90	-111980.22				
Y-8	5456.95	-111977.70				
Y-9	5468.09	-111961.10				
Y-10	5469.85	-111960.54				
Y-11	5470.88	-111959.40				
Y-12	5472.42	-111956.07				
Y-13	5475.04	-111943.36				
Y-14	5477.39	-111932.10				
Y-15	5478.26	-111919.35				
Y-16	5477.94	-111907.86				
Y-17	5476.33	-111889.65				
Y-18	5476.92	-111890.77				
Y-19	5479.83	-111894.17				
Y-20	5482.53	-111895.65				
Y-21	5483.70	-111895.83				
Y-22	5499.22	-111898.20				
Y-23	5499.33	-111898.21				
Y-24	5531.23	-111901.34				
Y-25	5527.67	-111914.67				
Y-26	5538.52	-111943.13				
Y-27	5530.58	-111956.88				
Y-28	5519.61	-111974.08				

著しい危害のおそれのある土地の座標					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
R-1	5492.26	-111976.13			
R-2	5489.01	-111987.48			
R-3	5482.21	-111994.90			
R-4	5458.33	-111998.83			
R-5	5438.79	-111987.29			
R-6	5438.19	-111981.10			
R-7	5442.72	-111980.93			
R-8	5442.93	-111980.92			
R-9	5442.96	-111985.42			
R-10	5464.10	-111976.89			
R-11	5471.90	-111975.82			
R-12	5474.25	-111974.47			
R-13	5478.57	-111967.49			
R-14	5483.76	-111954.15			
R-15	5490.22	-111939.99			
R-16	5489.14	-111929.06			
R-17	5490.06	-111914.99			
R-18	5488.57	-111896.57			
R-19	5499.22	-111898.20			
R-20	5499.33	-111898.21			
R-21	5508.31	-111899.09			
R-22	5508.40	-111915.00			
R-23	5513.93	-111936.14			
R-24	5509.90	-111948.30			
R-25	5500.20	-111963.63			