## 急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地等の座標一覧

調査年度

平成27年度

急傾斜地の位置	箇所番号	II -4969	箇所名		古茂口4	所在地	館山市古茂口	
			•					
	<b>危害のおそれのある土地の座標</b>				著しい危	き害のおそれの	ある土地の座標	

	危	害のおそれの	ある土地の座	標	
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	5455.43	-113282.10			
Y-2	5438.07	-113291.27			
Y-3	5427.53	-113282.23			
Y-4	5427.45	-113282.15			
Y-5	5424.92	-113279.73			
Y-6	5423.55	-113278.42			
Y-7	5420.22	-113271.03			
Y-8	5424.20	-113255.27			
Y-9	5435.11	-113247.67			
Y-10	5439.08	-113235.52			
Y-11	5439.48	-113236.14			
Y-12	5444.48	-113243.94			
Y-13	5444.54	-113244.03			
Y-14	5448.92	-113253.22			
Y-15	5449.01	-113253.41			
Y-16	5460.00	-113275.16			
Y-17	5459.07	-113276.67			

77.		<i>~</i>		7/2 4		
著しい危害のおそれのある土地の座標						
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	
R-1	5442.91	-113274.96				
R-2	5429.47	-113283.89				
R-3	5427.53	-113282.23				
R-4	5427.45	-113282.15				
R-5	5426.73	-113281.46				
R-6	5431.50	-113268.00				
R-7	5440.16	-113259.63				
R-8	5446.30	-113247.71				
R-9	5448.92	-113253.22				
R-10	5449.01	-113253.41				
R-11	5452.20	-113259.72				
R-12	5446.43	-113265.40				