
急傾斜地の崩壊区域調書



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地等の座標一覧

調査年度

平成27年度

| | 急傾斜地の位置 | 箇所番号 | II −5089 | 箇所名 | 茂名5 | 所在地 | 館山市茂名 |
|--|---------|------|----------|-----|-----|-----|-------|
|--|---------|------|----------|-----|-----|-----|-------|

| 地点記号 | X(m) | 害のおそれの Y(m) | 地点記号 | X(m) | Y(m) |
|------|--------|----------------|------|--------|---------|
| | | | 地無品力 | Λ(111) | 1 (111) |
| Y-1 | 428.12 | | | | |
| Y-2 | | -115729.34 | | | |
| Y-3 | 410.90 | | | | |
| Y-4 | 393.07 | -115728.24 | | | |
| Y-5 | | -115715.16 | | | |
| Y-6 | 395.92 | -115695.16 | | | |
| Y-7 | 395.94 | -115695.13 | | | |
| Y-8 | 402.35 | -115686.54 | | | |
| Y-9 | 403.70 | -115685.04 | | | |
| Y-10 | 410.39 | -115677.60 | | | |
| Y-11 | 417.80 | -115683.28 | | | |
| Y-12 | 428.01 | -115700.29 | | | |
| Y-13 | 432.79 | -115705.07 | | | |
| Y-14 | 432.86 | -115705.58 | | | |
| Y-15 | 431.99 | -115709.85 | | | |
| Y-16 | 430.93 | -115713.29 | | | |
| Y-17 | 430.36 | -115714.71 | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

| 人口り | | 1717エンビ | SH HIII) | X-71 | | |
|-------------------|--------|------------|----------|------|------|--|
| 著しい危害のおそれのある土地の座標 | | | | | | |
| 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | |
| R-1 | 428.12 | -115720.29 | | | | |
| R-2 | 426.15 | -115724.53 | | | | |
| R-3 | 417.29 | -115718.67 | | | | |
| R-4 | 405.72 | -115711.37 | | | | |
| R-5 | 390.73 | -115701.42 | | | | |
| R-6 | 395.92 | -115695.16 | | | | |
| R-7 | 395.94 | -115695.13 | | | | |
| R-8 | 400.63 | -115688.85 | | | | |
| R-9 | 415.37 | -115697.41 | | | | |
| R-10 | 422.63 | -115713.12 | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| <u> </u> | | | | | | |
| | | | | | | |