
## 急 傾 斜 地 の 崩 壊 区 域 調 書



## 急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地等の座標一覧

調査年度 2024

急傾斜地の位置	箇所番号	I −021K2034	箇所名	須和田5	所在地	市川市須和田2丁目

地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-29167.76	7469.16			
Y-2	-29183.65	7471.05			
Y-3	-29187.63	7472.05			
Y-4	-29198.40	7473.13			
Y-5	-29202.09	7474.63			
Y-6	-29202.09	7474.64			
Y-7	-29202.10	7474.64			
Y-8	-29202.10	7474.63			
Y-9	-29206.53	7472.52			
Y-10	-29207.85	7465.38			
Y-11	-29208.35	7462.69			
Y-12	-29209.20	7458.07			
Y-13	-29209.56	7456.13			
Y-14	-29211.01	7448.23			
Y-15	-29207.90	7447.58			
Y-16	-29207.89	7447.58			
Y-17	-29203.90	7446.64			
Y-18	-29197.00	7444.94			
Y-19	-29183.06	7442.49			
Y-20	-29183.07	7443.30			
Y-21	-29173.14	7434.82			
Y-22	-29170.53	7438.70			
Y-23	-29167.57	7443.13			
Y-24	-29162.98	7449.97			
Y-25	-29159.33	7455.40			
Y-26	-29155.09	7461.73		_	

	著しい	<b>、危害のおそれ</b>	ιのある土地の	座標	
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
R−1	-29207.85	7465.38			
R-2	-29208.35	7462.69			
R-3	-29204.77	7462.17			
R-4	-29204.58	7463.06			
R-5	-29204.24	7464.63			
R-6	-29203.54	7467.89			
R-7	-29207.59	7466.79			