


急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図




急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度

令和5年度



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度 令和5年度

急傾斜地の位置 箇所番号 I-031K2024 箇所名 幸谷4 所在地 松戸市幸谷、二ツ木

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-19412.29	8198.20	Y30	-19426.70	8234.10	R1	-19406.90	8194.39	R29	-19472.54	8254.56
Y2	-19425.24	8197.01	Y31	-19425.56	8236.91	R2	-19409.49	8199.94	R30	-19467.60	8245.17
Y3	-19404.32	8205.70	Y32	-19422.14	8245.33	R3	-19397.97	8207.61	R31	-19469.43	8243.47
Y4	-19404.25	8205.72	Y33	-19421.16	8247.73	R4	-19392.82	8209.15	R32	-19472.53	8240.60
Y5	-19392.82	8209.15	Y34	-19418.37	8254.59	R5	-19391.32	8209.61			
Y6	-19390.03	8209.99	Y35	-19407.36	8247.75	R6	-19391.13	8203.34	R33	-19472.94	8261.95
Y7	-19386.43	8210.89	Y36	-19395.97	8239.49	R7	-19401.23	8190.40	R34	-19479.62	8260.39
Y8	-19383.71	8211.46	Y37	-19394.58	8228.81	R8	-19402.48	8191.28	R35	-19479.62	8260.39
Y9	-19383.10	8211.58	Y38	-19398.88	8222.16	R9	-19403.94	8192.31	R36	-19479.60	8262.21
Y10	-19373.92	8213.48	Y39	-19400.01	8220.41				R37	-19479.60	8262.21
Y11	-19373.94	8212.32	Y40	-19401.79	8217.66	R10	-19413.70	8205.80	R38	-19479.60	8262.21
Y12	-19380.60	8210.28	Y41	-19403.85	8215.21	R11	-19419.10	8212.19	R39	-19479.58	8265.27
Y13	-19381.35	8200.22	Y42	-19406.45	8212.40	R12	-19425.23	8221.09	R40	-19479.58	8265.27
Y14	-19381.74	8197.38	Y43	-19408.89	8210.18	R13	-19427.61	8231.89	R41	-19479.58	8265.62
Y15	-19382.77	8194.41	Y44	-19410.99	8208.27	R14	-19426.70	8234.10	R42	-19479.58	8265.62
Y16	-19384.25	8191.76				R15	-19425.56	8236.91	R43	-19472.78	8266.56
Y17	-19385.88	8189.96	Y45	-19478.96	8234.63	R16	-19424.99	8238.31			
Y18	-19390.42	8187.06	Y46	-19488.28	8247.28	R17	-19418.16	8234.15	R44	-19488.71	8259.82
Y19	-19392.96	8185.83	Y47	-19486.82	8256.64	R18	-19404.45	8224.99	R45	-19495.75	8258.25
Y20	-19393.70	8186.20	Y48	-19482.78	8266.71	R19	-19405.02	8213.95	R46	-19495.75	8258.25
Y21	-19394.56	8186.63	Y49	-19481.66	8266.70	R20	-19406.45	8212.40	R47	-19496.60	8270.09
Y22	-19396.79	8187.74	Y50	-19472.78	8266.57	R21	-19408.89	8210.18	R48	-19495.46	8274.28
Y23	-19400.17	8189.65	Y51	-19472.22	8266.56	R22	-19410.99	8208.27	R49	-19495.24	8275.07
Y24	-19402.48	8191.28	Y52	-19465.08	8266.56				R50	-19492.63	8272.89
Y25	-19403.94	8192.31	Y53	-19460.69	8266.56	R23	-19473.51	8239.69	R51	-19492.63	8272.89
			Y54	-19455.08	8266.56	R24	-19480.86	8250.72	R52	-19487.87	8266.94
Y26	-19421.17	8199.01	Y55	-19455.96	8265.10	R25	-19480.32	8258.43	R53	-19488.05	8265.38
Y27	-19432.47	8201.04	Y56	-19455.88	8262.27	R26	-19477.50	8266.64	R54	-19488.29	8263.36
Y28	-19431.01	8209.96	Y57	-19454.18	8257.61	R27	-19472.78	8266.57			
Y29	-19430.09	8225.79	Y58	-19460.76	8251.51	R28	-19473.64	8260.26	R55	-19658.60	8271.03

平面直角座標系: 第Ⅸ系(測地成果2011)

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度 令和5年度

急傾斜地の位置 箇所番号 I-031K2024 箇所名 幸谷4 所在地 松戸市幸谷、二ツ木

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y59	-19461.51	8250.81	Y87	-19579.92	8266.12	R56	-19674.12	8263.78	R86	-19726.60	8382.09
Y60	-19469.43	8243.47	Y88	-19589.33	8279.72	R57	-19687.10	8270.50	R87	-19723.20	8372.11
Y61	-19472.53	8240.60	Y89	-19591.22	8282.59	R58	-19699.91	8285.91	R88	-19718.18	8367.85
			Y90	-19594.28	8287.11	R59	-19715.47	8309.23	R89	-19710.75	8352.67
Y62	-19473.12	8256.56	Y91	-19600.99	8296.72	R60	-19715.20	8331.68	R90	-19709.50	8353.09
Y63	-19479.66	8254.67	Y92	-19623.53	8326.59	R61	-19713.02	8339.49	R91	-19703.88	8343.34
Y64	-19479.66	8254.67	Y93	-19635.87	8342.51	R62	-19718.11	8350.13	R92	-19704.90	8330.41
Y65	-19489.52	8252.87	Y94	-19650.88	8360.72	R63	-19724.92	8347.80	R93	-19702.55	8315.26
Y66	-19498.45	8245.60	Y95	-19663.56	8375.04	R64	-19727.05	8359.42	R94	-19689.14	8296.09
Y67	-19498.45	8245.60	Y96	-19677.09	8389.87	R65	-19737.27	8361.58	R95	-19679.12	8279.63
Y68	-19498.62	8262.71	Y97	-19689.39	8402.40	R66	-19742.71	8371.59	R96	-19670.32	8269.39
Y69	-19498.08	8264.69	Y98	-19698.92	8411.75	R67	-19746.59	8381.83	R97	-19657.95	8272.29
Y70	-19495.46	8274.28	Y99	-19701.32	8414.14	R68	-19750.05	8389.19	R98	-19657.95	8272.29
Y71	-19494.16	8279.01	Y100	-19714.40	8427.33	R69	-19755.15	8393.26	R99	-19658.00	8272.19
Y72	-19492.33	8285.72	Y101	-19727.92	8440.48	R70	-19762.22	8403.07	R100	-19658.00	8272.19
Y73	-19491.52	8288.65	Y102	-19739.34	8450.49	R71	-19764.09	8415.72	R101	-19658.60	8271.03
Y74	-19489.11	8289.42	Y103	-19753.50	8462.49	R72	-19771.13	8432.50			
Y75	-19489.11	8289.42	Y104	-19770.18	8475.14	R73	-19778.35	8441.97			
Y76	-19486.01	8282.87	Y105	-19786.31	8486.88	R74	-19785.89	8454.63			
Y77	-19479.46	8281.47	Y106	-19800.90	8498.89	R75	-19782.82	8455.83			
Y78	-19479.46	8281.47	Y107	-19816.95	8509.16	R76	-19779.00	8457.32			
Y79	-19472.14	8284.84	Y108	-19827.16	8514.86	R77	-19776.30	8458.37			
Y80	-19472.38	8277.90	Y109	-19824.49	8519.62	R78	-19773.58	8459.38			
Y81	-19472.49	8274.85	Y110	-19821.87	8524.28	R79	-19766.42	8448.09			
Y82	-19472.78	8266.56	Y111	-19820.25	8527.15	R80	-19761.05	8438.05			
Y83	-19472.96	8261.27	Y112	-19819.19	8529.04	R81	-19753.24	8421.30			
			Y113	-19815.36	8535.87	R82	-19749.15	8415.01			
Y84	-19551.18	8256.22	Y114	-19804.46	8528.72	R83	-19737.56	8401.44			
Y85	-19562.75	8257.10	Y115	-19788.41	8518.09	R84	-19738.19	8393.42			
Y86	-19562.75	8257.10	Y116	-19772.73	8507.04	R85	-19732.24	8390.10			

平面直角座標系: 第Ⅸ系(測地成果2011)

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度 令和5年度

急傾斜地の位置 箇所番号 I-031K2024 箇所名 幸谷4 所在地 松戸市幸谷、二ツ木

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y117	-19755.90	8495.05	Y146	-19607.66	8330.79						
Y118	-19739.43	8482.05	Y147	-19598.21	8317.50						
Y119	-19724.45	8469.81	Y148	-19589.52	8303.51						
Y120	-19711.48	8458.65	Y149	-19585.58	8299.22						
Y121	-19697.08	8445.50	Y150	-19579.53	8285.16						
Y122	-19684.34	8433.96	Y151	-19585.60	8280.16						
Y123	-19670.54	8420.70	Y152	-19587.25	8278.80						
Y124	-19657.78	8407.28	Y153	-19588.18	8278.04						
Y125	-19644.29	8392.59	Y154	-19590.36	8276.25						
Y126	-19629.16	8375.64	Y155	-19595.90	8271.69						
Y127	-19614.61	8357.70	Y156	-19607.53	8287.97						
Y128	-19602.18	8342.65	Y157	-19618.74	8302.43						
Y129	-19590.19	8326.88	Y158	-19629.33	8315.92						
Y130	-19580.80	8309.14	Y159	-19640.81	8330.53						
Y131	-19571.79	8300.35	Y160	-19652.72	8345.29						
Y132	-19569.34	8296.52	Y161	-19664.03	8359.06						
Y133	-19558.42	8279.45	Y162	-19676.36	8373.51						
Y134	-19559.03	8279.07	Y163	-19688.27	8386.25						
Y135	-19554.66	8278.66	Y164	-19699.43	8397.31						
Y136	-19554.63	8278.50	Y165	-19710.88	8408.87						
Y137	-19553.12	8268.77	Y166	-19703.32	8414.34						
Y138	-19552.83	8266.89	Y167	-19702.78	8414.73						
Y139	-19552.58	8265.27	Y168	-19701.08	8415.96						
			Y169	-19700.74	8416.20						
Y140	-19690.06	8423.93									
Y141	-19662.40	8396.11	Y170	-19641.59	8240.02						
Y142	-19656.69	8388.94	Y171	-19653.43	8244.38						
Y143	-19652.19	8385.12	Y172	-19657.78	8249.72						
Y144	-19640.16	8371.47	Y173	-19662.26	8256.31						
Y145	-19619.09	8345.56	Y174	-19663.18	8258.37						

平面直角座標系: 第Ⅸ系(測地成果2011)

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度 令和5年度

急傾斜地の位置 箇所番号 I-031K2024 箇所名 幸谷4 所在地 松戸市幸谷、二ツ木

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y175	-19664.38	8259.73	Y205	-19738.46	8424.77						
Y176	-19664.38	8259.73	Y206	-19723.93	8407.78						
Y177	-19677.79	8258.38	Y207	-19725.25	8398.02						
Y178	-19694.15	8262.44	Y208	-19719.86	8397.24						
Y179	-19710.17	8276.22	Y209	-19713.56	8390.58						
Y180	-19728.37	8303.21	Y210	-19711.31	8381.02						
Y181	-19724.50	8332.82	Y211	-19706.96	8378.51						
Y182	-19724.62	8334.60	Y212	-19695.61	8357.87						
Y183	-19727.85	8346.79	Y213	-19695.61	8357.87						
Y184	-19738.07	8343.28	Y214	-19690.79	8348.85						
Y185	-19735.75	8351.17	Y215	-19688.77	8328.44						
Y186	-19753.33	8349.55	Y216	-19688.59	8321.77						
Y187	-19759.23	8360.83	Y217	-19677.68	8306.92						
Y188	-19765.16	8371.11	Y218	-19668.28	8292.02						
Y189	-19767.55	8382.96	Y219	-19661.06	8283.05						
Y190	-19774.97	8384.04	Y220	-19653.27	8281.45						
Y191	-19778.55	8388.15	Y221	-19653.27	8281.45						
Y192	-19784.34	8405.32	Y222	-19644.49	8274.05						
Y193	-19786.53	8424.04	Y223	-19642.02	8269.93						
Y194	-19793.74	8434.07	Y224	-19638.21	8264.28						
Y195	-19796.89	8450.34	Y225	-19637.20	8262.59						
Y196	-19782.82	8455.83	Y226	-19632.53	8262.67						
Y197	-19779.00	8457.32	Y227	-19634.59	8257.53						
Y198	-19776.30	8458.37	Y228	-19636.24	8253.39						
Y199	-19767.67	8461.57	Y229	-19636.39	8253.02						
Y200	-19766.69	8461.93	Y230	-19638.23	8248.43						
Y201	-19758.30	8465.04									
Y202	-19753.80	8454.57	Y231	-19804.70	8476.49						
Y203	-19749.11	8444.61	Y232	-19820.34	8484.73						
Y204	-19741.56	8427.30	Y233	-19836.68	8494.26						

平面直角座標系: 第Ⅸ系(測地成果2011)

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度

令和5年度

急傾斜地の位置

箇所番号

I-031K2024

箇所名

幸谷4

所在地

松戸市幸谷、二ツ木

[illegible]

平面直角座標系:第Ⅸ系(測地成果2011)