急傾斜地の崩壊区域調書

Y11 Y12 Y10 Y11 Y12 Y13 Y14 Y14 Y25 Y15 Y16 Y27 Y27 Y28 Y27 Y28 Y29 Y39 Y39 Y39 Y31 Y34 Y34 Y34	式5-4 危害のおそれのある土 急傾斜地の位置 1		031K2060	秋山4	所在地	調査年度 松戸市秋山1丁目	2023
Y35	Y6 Y5 Y4	Y39 Y38 Y37 Y36	Y8 Y41 Y22 Y21	Y42 Y23 Y24 Y20	Y25 →	Y11 Y12 Y13 Y26 Y14 Y15 Y16 Y27 Y28 Y30 Y31	N.

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度

2023

急傾斜地の位置 箇所番号 *I −031K2060* **箇所名 参所名 参 が**山4 **が**山4 **が一た地 が一た地 が**の**は**

危害のおそれのある区域の座標(土砂災害警戒区域)					著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)						
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-26069.57	8644.56	Y30	-26061.65	8709.52						
Y2	-26071.93	8624.36	Y31	-26070.33	8711.09						
Y3	-26064.81	8623.25	Y32	-26073.20	8693.12						
Y4	-26062.05	8622.82	Y33	-26076.50	8672.68						
Y5	-26059.48	8622.41	Y34	-26079.70	8652.94						
Y6	-26057.20	8622.06	Y35	-26082.68	8633.53						
Y7	-26049.60	8620.87	Y36	-26077.19	8632.67						
Y8	-26046.06	8640.25	Y37	-26072.80	8631.98						
Y9	-26042.53	8660.12	Y38	-26071.27	8631.74						
Y10	-26038.81	8679.26	Y39	-26069.58	8631.48						
Y11	-26034.99	8698.93	Y40	-26061.39	8630.19						
Y12	-26033.91	8704.50	Y41	-26056.83	8649.96						
Y13	-26043.33	8706.22	Y42	-26052.28	8669.60						
Y14	-26043.75	8706.29									
Y15	-26047.49	8706.97									
Y16	-26048.13	8707.09									
Y17	-26060.22	8709.29									
Y18	-26060.97	8704.59									
Y19	-26064.13	8684.58									
Y20	-26067.32	8664.28									
Y21	-26068.21	8658.83									
Y22	-26069.57	8644.56									
Y23	-26052.28	8669.60									
Y24	-26050.89	8675.88									
Y25	-26048.79	8687.99									
Y26	-26045.36	8706.55									
Y27	-26056.85	8708.64									
Y28	-26058.58	8708.96									
Y29	-26060.49	8709.30									

平面直角座標系:第IX系(測地成果2011)