
## 急傾斜地の崩壊区域調書



## 急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度

令和5年度

急傾斜地の位置 | 箇所番号 | I-031K2067 | 箇所名 | 小金原1 | 小金原1 | 所在地 | 松戸市小金原1丁目

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-19469.56	9546.89	Y30	-19389.63	9496.66						
Y2	-19455.97	9550.24	Y31	-19390.22	9496.38						
Y3	-19433.09	9554.21	Y32	-19391.66	9495.70						
Y4	-19432.95	9552.45	Y33	-19394.81	9494.20						
Y5	-19431.72	9552.71	Y34	-19400.70	9491.41						
Y6	-19421.90	9554.80	Y35	-19393.54	9481.82						
Y7	-19419.74	9545.16	Y36	-19386.35	9481.75						
Y8	-19419.10	9542.31	Y37	-19386.36	9489.36						
Y9	-19418.73	9540.66	Y38	-19386.37	9491.75						
Y10	-19418.29	9538.71	Y39	-19386.37	9493.35						
Y11	-19416.54	9530.90	Y40	-19386.37	9495.02						
Y12	-19426.51	9528.77	Y41	-19386.38	9498.21						
Y13	-19435.38	9526.87	Y42	-19386.38	9498.21						
Y14	-19434.87	9524.32									
Y15	-19446.09	9526.24									
Y16	-19448.01	9531.94									
Y17	-19450.97	9526.97									
Y18	-19464.20	9523.91									
Y19	-19465.68	9530.26									
Y20	-19466.47	9533.65									
Y21	-19467.29	9537.15									
Y22	-19467.99	9540.15									
Y23	-19381.19	9500.67									
Y24	-19385.78	9501.99									
Y25	-19386.39	9503.35									
Y26	-19386.38	9500.43									
Y27	-19386.38	9500.43								_	
Y28	-19387.43	9497.71									
Y29	-19387.43	9497.71									

平面直角座標系:第IX系(測地成果2011)