


急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図


調査年度

2023

急傾斜地の位置	箇所番号	I-031K2078	箇所名	小根本1	所在地	松戸市小根本、岩瀬
---------	------	------------	-----	------	-----	-----------



1:1,500



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧(1/3)

調査年度	2023
------	------

急傾斜地の位置	箇所番号	I-031K2078	箇所名	小根本1	所在地	松戸市小根本、岩瀬
---------	------	------------	-----	------	-----	-----------

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-23695.10	6721.49	Y30	-23673.61	6703.50	R1	-23588.32	6687.87			
Y2	-23702.83	6723.37	Y31	-23675.66	6703.28	R2	-23591.75	6686.22			
Y3	-23702.67	6722.37	Y32	-23676.29	6703.21	R3	-23600.85	6681.86			
Y4	-23707.02	6717.33				R4	-23594.87	6666.50			
Y5	-23720.32	6713.68	Y33	-23671.26	6711.53	R5	-23597.11	6665.78			
Y6	-23718.84	6705.73	Y34	-23673.35	6711.29	R6	-23598.75	6656.99			
Y7	-23718.31	6702.86	Y35	-23671.26	6696.86	R7	-23603.49	6649.45			
Y8	-23717.98	6701.09	Y36	-23670.77	6693.47	R8	-23605.06	6639.40			
Y9	-23717.72	6699.68	Y37	-23670.15	6689.21	R9	-23601.57	6637.88			
Y10	-23716.16	6691.26	Y38	-23669.51	6684.80	R10	-23598.80	6636.68			
Y11	-23702.63	6694.96	Y39	-23668.72	6679.32	R11	-23597.72	6636.21			
Y12	-23698.17	6697.28	Y40	-23666.86	6679.53	R12	-23597.64	6646.18			
Y13	-23698.16	6697.29	Y41	-23667.61	6684.95	R13	-23590.02	6654.70			
Y14	-23692.54	6699.44	Y42	-23668.22	6689.44	R14	-23590.77	6666.05			
Y15	-23693.36	6706.48	Y43	-23668.81	6693.70	R15	-23580.63	6667.01			
Y16	-23693.69	6709.37	Y44	-23669.31	6697.38	R16	-23583.89	6689.99			
Y17	-23693.92	6711.36	Y45	-23671.26	6711.53	R17	-23588.32	6687.87			
Y18	-23694.19	6713.62									
Y19	-23695.10	6721.49	Y46	-23622.22	6705.11	R18	-23757.56	6823.68			
			Y47	-23634.94	6688.89	R19	-23761.19	6821.21			
Y20	-23676.29	6703.21	Y48	-23635.80	6687.80	R20	-23754.15	6813.92			
Y21	-23685.60	6702.22	Y49	-23637.77	6685.28	R21	-23751.50	6816.01			
Y22	-23684.25	6691.90	Y50	-23638.88	6683.86	R22	-23750.92	6816.47			
Y23	-23675.18	6693.00	Y51	-23643.94	6677.41	R23	-23757.56	6823.68			
Y24	-23674.32	6693.10	Y52	-23641.01	6674.97						
Y25	-23672.61	6693.31	Y53	-23640.99	6674.95						
Y26	-23671.90	6693.40	Y54	-23635.78	6669.91						
Y27	-23657.56	6695.13	Y55	-23632.22	6677.15						
Y28	-23658.53	6705.11	Y56	-23631.37	6678.89						
Y29	-23672.83	6703.58	Y57	-23630.27	6681.14						

平面直角座標系: 第Ⅸ系(測地成果2011)

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧(2/3)

調査年度	2023
所在地	松戸市小根本、岩瀬

急傾斜地の位置	箇所番号	I-031K2078	箇所名	小根本1		所在地	松戸市小根本、岩瀬				
危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y58	-23628.57	6684.60	Y87	-23606.28	6679.25						
Y59	-23625.77	6690.29									
Y60	-23626.83	6692.69	Y88	-23634.01	6641.98						
Y61	-23617.35	6704.58	Y89	-23634.16	6639.18						
Y62	-23622.22	6705.11	Y90	-23628.96	6638.89						
			Y91	-23624.17	6638.62						
Y63	-23606.28	6679.25	Y92	-23624.08	6638.62						
Y64	-23609.67	6677.63	Y93	-23622.28	6638.52						
Y65	-23615.30	6674.93	Y94	-23614.09	6638.05						
Y66	-23609.11	6665.75	Y95	-23614.08	6639.32						
Y67	-23609.14	6665.24	Y96	-23622.40	6640.43						
Y68	-23611.03	6660.20	Y97	-23623.99	6640.64						
Y69	-23613.42	6656.42	Y98	-23624.09	6640.66						
Y70	-23615.12	6649.68	Y99	-23629.01	6641.31						
Y71	-23623.82	6650.80	Y100	-23634.01	6641.98						
Y72	-23623.87	6645.35									
Y73	-23623.91	6640.80	Y101	-23602.94	6589.74						
Y74	-23623.91	6640.70	Y102	-23603.81	6589.83						
Y75	-23623.92	6638.79	Y103	-23603.36	6597.92						
Y76	-23623.99	6630.70	Y104	-23611.34	6606.76						
Y77	-23617.42	6625.68	Y105	-23617.59	6608.60						
Y78	-23590.77	6633.08	Y106	-23620.93	6609.58						
Y79	-23578.05	6627.68	Y107	-23623.26	6610.26						
Y80	-23577.82	6636.06	Y108	-23625.70	6611.34						
Y81	-23569.88	6649.43	Y109	-23626.60	6611.73						
Y82	-23568.30	6666.82	Y110	-23633.90	6615.11						
Y83	-23562.52	6667.50	Y111	-23634.79	6615.52						
Y84	-23567.66	6697.78	Y112	-23638.35	6602.01						
Y85	-23588.32	6687.87	Y113	-23642.52	6599.04						
Y86	-23591.75	6686.22	Y114	-23637.94	6597.72						

平面直角座標系：第Ⅸ系(測地成果2011)

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧(3/3)

調査年度	2023
所在地	松戸市小根本、岩瀬

急傾斜地の位置	箇所番号	I-031K2078	箇所名	小根本1	所在地	松戸市小根本、岩瀬
---------	------	------------	-----	------	-----	-----------

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y115	-23641.18	6581.47	Y144	-23751.50	6816.01						
Y116	-23645.54	6575.47	Y145	-23746.31	6820.12						
Y117	-23643.68	6549.81	Y146	-23752.93	6826.84						
Y118	-23644.49	6544.27	Y147	-23757.24	6823.90						
Y119	-23655.07	6536.06	Y148	-23761.19	6821.21						
Y120	-23664.87	6524.54	Y149	-23765.41	6818.34						
Y121	-23661.46	6521.48	Y150	-23771.77	6814.01						
Y122	-23657.42	6517.86									
Y123	-23657.13	6517.59									
Y124	-23655.26	6515.92									
Y125	-23649.69	6510.91									
Y126	-23640.86	6511.55									
Y127	-23640.76	6510.60									
Y128	-23621.15	6512.87									
Y129	-23604.51	6532.19									
Y130	-23606.71	6534.71									
Y131	-23603.73	6534.57									
Y132	-23604.64	6552.29									
Y133	-23610.31	6550.49									
Y134	-23608.62	6554.69									
Y135	-23606.01	6570.99									
Y136	-23602.66	6571.64									
Y137	-23602.94	6589.74									
Y138	-23771.77	6814.01									
Y139	-23773.68	6812.71									
Y140	-23765.61	6804.86									
Y141	-23764.76	6805.54									
Y142	-23757.76	6811.06									
Y143	-23754.15	6813.92									

平面直角座標系: 第Ⅸ系(測地成果2011)