急傾斜地の崩壊区域調書

5-4 危害のおそれのあ 急傾斜地の位置	る土地等の座標位	置図		() == 4 == .			調査年度	令和5年度	=
急傾斜地の位置	箇所番号	<i>I −031K2145</i>	箇所名	東平賀1	所在地	松戸市東平賀			
									Ν
									٨
									,
				Va					
				Y3					
				Y4 Y2					
				Y4 Y6 Y7 Y5					
				9 11					
			1	78 🥥					
				Y12 OY14					
				Y12 Y14 Y13 Y11					
				13					
				Y10					
								1:1,000	
							0	25	5
								20	5
									エ

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度

令和5年度

急傾斜地の位置	箇所番号	I −031K2145	箇所名	東平賀1	所在地	松戸市東平賀

危害のおそれのある区域の座標(土砂災害警戒区域)					著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)						
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-18126.66	9052.91									
Y2	-18119.86	9044.63									
Y3	-18114.45	9036.06									
Y4	-18121.77	9029.55									
Y5	-18122.82	9028.62									
Y6	-18123.64	9027.89									
Y7	-18124.80	9026.87									
Y8	-18131.12	9021.25									
Y9	-18139.46	9029.10									
Y10	-18147.10	9037.83									
Y11	-18140.05	9043.03									
Y12	-18139.05	9043.77									
Y13	-18137.92	9044.60									
Y14	-18136.82	9045.41									