
| 頃 斜 地 | 0703 C1 | いめる | 土地の区域の | | | | | | | | | | 調査年 | 度 | 2 | 024 |
|-------|---------------------|-------------------------|---|---------------------|----------------|------------|----------------|--------------|----------------------------|--------------|----|------|-----|--------|----------|-----|
| 吸 叶 地 | の位 | 置 | 箇所番号 | I -041K. | <i>X2142-2</i> | 箇所名 | | 鷲野谷4 | | 所在地 | 柏用 | 了鷲野谷 | | | | |
| | | | | | | | | | | | | | | | N | |
| | | | | | | | į | Y-07 Y-08 | Y-09 | | | | | | | |
| | | | | | | Y-06 | | R-05 | •Y−10 •Y−11 -06 R−07 | R-08 | | | | | | |
| | | | | | , | Y-04 R-03 | R-04 | R-12 R-13 | R-11 Y-15 | R-09 Y-13 | | | | | | |
| | ● 危: | 害のおそれ | 凡 例 1のある土地等の! | 端点 | , | Y-04 R-03 | R-04 | R-13 Y-17 | R-11 Y-15 | R-09 Y-13 | | | | | | |
| | 危 [:] 著 | 害のおそれ | 凡 例 れのある土地等の れのある土地の区 のおそれのある土地 れのある土地の端 | 或 也の区域 | | Y-04 R-03 | R-01 1 Y-02 | R-13 Y-17 | R-11 Y-15 | R-09 Y-13 | | | | | | |
| I | 危 著 Y-1 危 | 害のおそれ しい危害の 害のおそれ | れのある土地等の! れのある土地の区: のおそれのある土± | 域 也の区域 点 地点記号 | | Y-04 R-03 | R-01 1 Y-02 | R-13 Y-17 | R-11 Y-15 | R-09 Y-13 | | | 1: | :1,000 | | |
| I | 危 著 Y-1 危 | 害のおそれ しい危害の 害のおそれ | れのある土地等の! れのある土地の区! のおそれのある土± れのある土地の端! | 域 也の区域 点 地点記号 | | Y-04 R-03 | R-01 1 Y-02 | R-13 Y-17 | R-11 Y-15 | R-09 Y-13 | | 50 | 1: | :1,000 | 100 m | |

様式5-5 危害のおそれのある土地の区域の座標一覧 急傾斜地の位置 箇所番号 I-041K2142-2 箇所名 鷲野谷4 所在地 柏市鷲野谷

| | 危害 <i>0</i> | つおそれのある | 6土地の区域 <i>0</i> |)座標 | 著しい危害のおそれのある土地の区域の座標 | | | | | | | |
|------|-------------|----------|------------------|------|----------------------|------------------|-----------|----------|------------------|----------|------|--|
| 地点記号 | X(m) | Y(m) | 地点記 号 | X(m) | Y(m) | 地点記 号 | X(m) | Y(m) | 地点記 号 | X(m) | Y(m) | |
| Y-01 | -17023.74 | 19145.73 | | | | R-01 | -17016.45 | 19140.15 | | | | |
| Y-02 | -17016.87 | 19140.47 | | | | R-02 | -17011.66 | 19136.49 | | | | |
| Y-03 | -17011.66 | 19136.49 | | | | R-03 | -17008.15 | 19133.68 | | | | |
| Y-04 | -17001.44 | 19128.30 | | | | R-04 | -16999.55 | 19139.69 | | | | |
| Y-05 | -16993.64 | 19122.05 | | | | R-05 | -16985.82 | 19150.07 | | | | |
| Y-06 | -16987.07 | 19129.41 | | | | R-06 | -16987.65 | 19160.91 | | | | |
| Y-07 | -16968.24 | 19145.38 | | | | R-07 | -16990.17 | 19171.85 | | | | |
| Y-08 | -16970.06 | 19157.30 | | | | R-08 | -16993.04 | 19172.50 | | | | |
| Y-09 | -16971.97 | 19167.74 | | | | R-09 | -16996.32 | 19173.44 | | | | |
| Y-10 | -16977.27 | 19168.94 | | | | R-10 | -16998.39 | 19174.03 | | | | |
| Y-11 | -16981.73 | 19169.94 | | | | R-11 | -17002.20 | 19163.93 | | | | |
| Y-12 | -16993.04 | 19172.50 | | | | R-12 | -17004.83 | 19155.22 | | | | |
| Y-13 | -16996.32 | 19173.44 | | | | R-13 | -17009.47 | 19147.66 | | | | |
| Y-14 | -17005.92 | 19176.19 | | | | | | | | | | |
| Y-15 | -17014.32 | 19166.47 | | | | | | | | | | |
| Y-16 | -17020.73 | 19159.64 | | | | | | | | | | |
| Y-17 | -17018.52 | 19154.77 | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | <u> </u> | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |



様式5-5 危害のおそれのある土地の区域の座標一覧 調査年度 2024 急傾斜地の位置 箇所番号 I-041K2142-3 箇所名 *鷲野谷4* 所在地 *柏市鷲野谷*

| | 危害の | りおそれのある | る土地の区域 <i>の</i> |)座標 | | 著しい危害のおそれのある土地の区域の座標 | | | | | | | |
|------|-----------|----------|-----------------|------|------|----------------------|-----------|----------|--------|------------|--------|--|--|
| 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | | |
| Y-01 | -16962.04 | 19266.95 | | | | R-01 | -16947.31 | 19253.89 | | | | | |
| Y-02 | -16947.79 | 19254.32 | | | | R-02 | -16941.24 | 19248.50 | | | | | |
| Y-03 | -16941.24 | 19248.50 | | | | R-03 | -16929.78 | 19238.47 | | | | | |
| Y-04 | -16923.33 | 19232.83 | | | | R-04 | -16916.90 | 19251.60 | | | | | |
| Y-05 | -16923.11 | 19232.64 | | | | R-05 | -16910.14 | 19265.83 | | | | | |
| Y-06 | -16915.80 | 19226.25 | | | | R-06 | -16903.51 | 19272.73 | | | | | |
| Y-07 | -16902.51 | 19240.04 | | | | R-07 | -16898.73 | 19274.03 | | | | | |
| Y-08 | -16895.77 | 19254.28 | | | | R-08 | -16884.73 | 19269.24 | | | | | |
| Y-09 | -16892.48 | 19257.92 | | | | R-09 | -16882.74 | 19272.88 | | | | | |
| Y-10 | -16893.34 | 19260.39 | | | | R-10 | -16881.07 | 19275.87 | | | | | |
| Y-11 | -16891.50 | 19256.81 | | | | R-11 | -16879.62 | 19278.49 | | | | | |
| Y-12 | -16887.28 | 19264.55 | | | | R-12 | -16896.73 | 19285.53 | | | | | |
| Y-13 | -16886.71 | 19265.59 | | | | R-13 | -16917.93 | 19288.90 | | | | | |
| Y-14 | -16882.74 | 19272.88 | | | | R-14 | -16927.96 | 19280.41 | | | | | |
| Y-15 | -16881.07 | 19275.87 | | | | R-15 | -16934.88 | 19266.31 | | | | | |
| Y-16 | -16873.00 | 19290.35 | | | | | | | | | | | |
| Y-17 | -16893.93 | 19297.82 | | | | | | | | | | | |
| Y-18 | -16930.27 | 19302.30 | | | | | | | | | | | |
| Y-19 | -16942.79 | 19292.97 | | | | | | | | | | | |
| Y-20 | -16949.86 | 19278.96 | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | 1 | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | 1 | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | • | | | | | • | | | ※測量座標系 | JGD2011 亚南 | 直角座標第6 | | |

| 5 斜地の位置 箇 | 前所番号 <i>I −04</i> | | | 会分 mマ /√) / | | /-/- 一一章 全世 四マ /-) | 調査年度 | • |
|--|---------------------|--------------------|----------------------|--|-------------------------------------|--------------------|---------|---|
| | | 41K2142-4 | 箇所名 | 鷲野谷4 | 所在地 | 柏市鷲野谷 | | N |
| | | | | | | | | |
| | | | Υ- | R=07 R=06 R=13 Y=09 Y=09 | Y-18 Y-19 -12 Y-20 Y-21 | | | |
| | | | | | | | | |
| | | Y-07 ● Y | Y-06 Y-05 Y-02 | R-04 R-03 R-02 R-01 Y-25 Y-24 | Y-23 | | | |
| 「 ● 危害のおそれのあ 「 」危害のおそれのあ | ある土地等の端点 ある土地の区域 | | Y-06 Y-05 Y-02 | R-04 R-03 R-02 R-01 Y-25 | Y-23 | | | |
| ● 危害のおそれのあ 危害のおそれのあ 著しい危害のおそ Y-1 危害のおそれのあ | ある土地等の端点 | Y | Y-06 Y-05 Y-02 | R-04 R-03 R-02 R-01 Y-25 Y-24 | Y-23 | | 1:1,000 | |

様式5-5 危害のおそれのある土地の区域の座標一覧 急傾斜地の位置 箇所番号 I-041K2142-4 箇所名

*** 箇所名 | 第野谷4 | 所在地 | 柏市鷲野谷 | 1-041K2142-4 | 11-041K2142-4 | 11-

| | 危害の | りおそれのある | る土地の区域の |)座標 | 著しい危害のおそれのある土地の区域の座標 | | | | | | | |
|------|-----------|----------|------------------|------|----------------------|--------------|-----------|----------|------|------|------|--|
| 地点記号 | X(m) | Y(m) | 地点記 号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | |
| Y-01 | -16897.16 | 19279.81 | | | | R-01 | -16882.62 | 19292.42 | | | | |
| Y-02 | -16885.78 | 19274.35 | | | | R-02 | -16878.79 | 19290.12 | | | | |
| Y-03 | -16882.25 | 19272.63 | | | | R-03 | -16877.57 | 19289.38 | | | | |
| Y-04 | -16881.08 | 19269.40 | | | | R-04 | -16875.25 | 19288.04 | | | | |
| Y-05 | -16879.84 | 19265.58 | | | | R-05 | -16868.67 | 19297.31 | | | | |
| Y-06 | -16879.36 | 19264.08 | | | | R-06 | -16855.70 | 19295.32 | | | | |
| Y-07 | -16876.76 | 19256.07 | | | | R-07 | -16849.36 | 19297.11 | | | | |
| Y-08 | -16862.17 | 19279.92 | | | | R-08 | -16845.80 | 19298.66 | | | | |
| Y-09 | -16862.61 | 19280.70 | | | | R-09 | -16847.50 | 19303.91 | | | | |
| Y-10 | -16859.99 | 19285.37 | | | | R-10 | -16848.62 | 19307.27 | | | | |
| Y-11 | -16857.61 | 19281.13 | | | | <i>R</i> −11 | -16849.79 | 19310.77 | | | | |
| Y-12 | -16849.02 | 19282.11 | | | | R-12 | -16849.76 | 19308.24 | | | | |
| Y-13 | -16840.71 | 19282.88 | | | | R-13 | -16854.29 | 19305.63 | | | | |
| Y-14 | -16843.59 | 19291.82 | | | | <i>R</i> −14 | -16873.99 | 19304.62 | | | | |
| Y-15 | -16843.78 | 19292.40 | | | | | | | | | | |
| Y-16 | -16847.50 | 19303.91 | | | | | | | | | | |
| Y-17 | -16848.62 | 19307.27 | | | | | | | | | | |
| Y-18 | -16849.88 | 19311.02 | | | | | | | | | | |
| Y-19 | -16850.27 | 19319.99 | | | | | | | | | | |
| Y-20 | -16853.34 | 19321.36 | | | | | | | | | | |
| Y-21 | -16852.35 | 19318.42 | | | | | | | | | | |
| Y-22 | -16852.53 | 19318.28 | | | | | | | | | | |
| Y-23 | -16879.93 | 19312.79 | | | | | | | | | | |
| Y-24 | -16891.11 | 19297.54 | | | | | | | | | | |
| Y-25 | -16888.55 | 19296.00 | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |