


急傾斜地の崩壊区域調書

様式5-1 危害のおそれのある土地等の座標位置図



急傾斜地の崩壊区域調書

様式5-2 危害のおそれのある土地等の座標一覧(1/2)

調査年度 平成18年度

急傾斜地の位置			箇所番号			I -0480			箇所名			本町2			所在地			香取郡多古町多古								
危害のおそれのある区域の座標(土砂災害警戒区域)									危害のおそれのある区域の座標(土砂災害警戒区域)																	
地点記号			X(m)			Y(m)			地点記号			X(m)			Y(m)			地点記号			X(m)			Y(m)		
Y-1			57379.57			-28568.13																				
Y-2			57364.08			-28558.07																				
Y-3			57363.62			-28557.63																				
Y-4			57356.31			-28549.39																				
Y-5			57365.85			-28531.87																				
Y-6			57388.73			-28518.46																				
Y-7			57401.36			-28514.28																				
Y-8			57406.62			-28503.43																				
Y-9			57416.04			-28506.78																				
Y-10			57422.97			-28509.17																				
Y-11			57426.89			-28510.84																				
Y-12			57433.66			-28513.71																				
Y-13			57442.36			-28517.40																				
Y-14			57437.77			-28536.80																				
Y-15			57413.90			-28557.35																				
Y-16			57397.37			-28575.71																				
Y-17			57438.27			-28511.65																				
Y-18			57435.16			-28504.62																				
Y-19			57432.92			-28499.59																				
Y-20			57426.36			-28485.21																				
Y-21			57446.80			-28478.47																				
Y-22			57479.81			-28480.34																				
Y-23			57484.00			-28473.79																				
Y-24			57486.81			-28484.56																				
Y-25			57487.01			-28485.46																				
Y-26			57487.23			-28486.71																				
Y-27			57487.70			-28498.20																				
Y-28			57487.89			-28503.18																				
Y-29			57474.04			-28507.47																				
Y-30			57456.32			-28510.26																				

急傾斜地の崩壊区域調書

様式5-2 危害のおそれのある土地等の座標一覧(2/2)

調査年度

平成18年度

[illegible]