


急傾斜地の崩壊区域調査

様式5-4 危害のおそれのある土地等の座標位置図

調査年度	2024
------	------

急傾斜地の位置	箇所番号	II-021K2099	箇所名	本行徳1	所在地	市川市本行徳
---------	------	-------------	-----	------	-----	--------



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地等の座標一覧

調査年度 2024

急傾斜地の位置		箇所番号		II-021K2099		箇所名		本行徳1		所在地		市川市本行徳		
危害のおそれのある土地の座標						著しい危害のおそれのある土地の座標								
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-35221.96	9262.49				R-1	-35228.96	9248.65						
Y-2	-35254.75	9270.07				R-2	-35246.73	9256.43						
Y-3	-35265.96	9264.50				R-3	-35257.48	9251.59						
Y-4	-35284.86	9244.93				R-4	-35272.29	9236.44						
Y-5	-35294.16	9235.36				R-5	-35281.64	9224.97						
Y-6	-35288.86	9183.57				R-6	-35273.46	9191.88						
Y-7	-35284.22	9170.19				R-7	-35268.75	9177.67						
Y-8	-35282.28	9171.13				R-8	-35266.41	9178.80						
Y-9	-35275.22	9174.54				R-9	-35257.38	9183.82						
Y-10	-35266.41	9178.80				R-10	-35249.72	9188.08						
Y-11	-35257.38	9183.82				R-11	-35256.87	9200.31						
Y-12	-35248.81	9188.59				R-12	-35257.67	9215.53						
Y-13	-35232.92	9197.44				R-13	-35254.81	9225.62						
Y-14	-35242.41	9206.88				R-14	-35247.28	9234.00						
Y-15	-35231.93	9209.89				R-15	-35238.98	9238.76						
Y-16	-35235.16	9214.00				R-16	-35232.21	9239.39						
Y-17	-35236.81	9215.22				R-17	-35233.28	9231.78						
Y-18	-35233.90	9218.74				R-18	-35232.10	9228.19						
Y-19	-35217.03	9213.81				R-19	-35213.34	9217.60						
Y-20	-35213.86	9217.06				R-20	-35210.04	9220.97						
Y-21	-35210.04	9220.97				R-21	-35218.45	9235.58						
Y-22	-35207.01	9224.07				R-22	-35224.07	9243.40						
Y-23	-35204.77	9226.59												
Y-24	-35200.37	9231.54												
Y-25	-35198.12	9234.06												
Y-26	-35205.84	9246.22												
Y-27	-35212.85	9254.82												

平面直角座標系：第Ⅸ系(測地成果2011)

平面直角座標系:第IX系(測地成果2011)