


急傾斜地の崩壊区域調書

様式5-4 危害のおそれのある土地等の座標位置図

調査年度

2024



急傾斜地の崩壊区域調査

様式5-5 危害のおそれのある土地の座標一覧

調査年度

2024

急傾斜地の位置	箇所番号	II-022K2136		箇所名	大穴北10		所在地	船橋市大穴北7丁目			
危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-28399.03	19624.52				R1	-28395.20	19620.96			
Y2	-28392.83	19643.62				R2	-28383.70	19631.77			
Y3	-28388.51	19643.62				R3	-28375.51	19636.06			
Y4	-28377.38	19647.81				R4	-28366.64	19645.30			
Y5	-28375.59	19665.94				R5	-28366.45	19661.32			
Y6	-28370.44	19675.16				R6	-28360.36	19667.90			
Y7	-28359.52	19695.30				R7	-28345.49	19681.23			
Y8	-28349.42	19705.26				R8	-28334.15	19692.95			
Y9	-28339.72	19716.84				R9	-28323.75	19706.55			
Y10	-28327.26	19730.81				R10	-28313.12	19720.89			
Y11	-28316.94	19744.59				R11	-28303.77	19732.32			
Y12	-28290.88	19744.59				R12	-28287.65	19740.38			
Y13	-28284.79	19736.66				R13	-28284.79	19736.66			
Y14	-28281.13	19731.91				R14	-28288.11	19717.72			
Y15	-28278.55	19728.55				R15	-28296.23	19709.05			
Y16	-28275.04	19723.98				R16	-28304.88	19694.39			
Y17	-28274.72	19705.24				R17	-28316.90	19679.04			
Y18	-28281.19	19698.50				R18	-28330.98	19666.67			
Y19	-28289.53	19684.49				R19	-28348.93	19659.68			
Y20	-28303.46	19668.20				R20	-28355.63	19655.86			
Y21	-28319.62	19655.26				R21	-28355.52	19642.69			
Y22	-28335.54	19650.05				R22	-28362.53	19628.50			
Y23	-28339.88	19647.90				R23	-28374.31	19619.58			
Y24	-28340.38	19639.15				R24	-28391.71	19617.71			
Y25	-28349.18	19620.74									
Y26	-28364.76	19607.18									
Y27	-28379.26	19606.13									
Y28	-28380.62	19607.40									
Y29	-28386.58	19612.94									
Y30	-28391.71	19617.71									

平面直角座標系：第Ⅸ区(測地成果2011)

平面直角座標系：第Ⅸ系(測地成果2011)